



<b>Fan Heater, XH-1201</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>PSD Number</b>	2401-0052 / 2402-0098
<b>Product Type</b>	Electrical appliances and equipment – Fan Heater
<b>Product Identifiers</b>	Model Number: XH-1201 Additional identifiers: M0100000004988151, UKT002059, SS50003000045430808078
<b>Product Description</b>	White oval-shaped fan heater with gold rim and black grating, supplied with black power supply cord and three-pin plug in white cardboard packaging.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	Unknown
<b>Risk Level</b>	Serious
<b>Risk Type</b>	Fire
<b>Risk Description</b>	<p>The product presents a serious risk of fire as the overheat protection device was not fixed, and would not function when required. This could cause the product to overheat and ignite under fault conditions. The plug also had pins with a distinct step between the sleeve and the metal parts which could cause damage to the socket and undue wear and tear to the sleeve over time. Additionally, the fuse did not contain any ballast, which is required for the proper functioning of the fuse under fault conditions, thereby presenting a risk of fire.</p> <p>The product also required improvements to marking, labelling and documentation.</p> <p>The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs &amp; Sockets (Safety) Regulations 1994.</p>
<b>Corrective Measures</b>	The import has been rejected at the border and destroyed.
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards