




Honda Marine Outboard Engines																									
Aspect	Details																								
Images																									
PSD Number	2310-0276																								
Product Type	Recreational crafts – Marine outboard engine																								
Product Identifiers	Brand: Honda <table border="1"> <thead> <tr> <th>Model</th> <th>From</th> <th>To</th> </tr> </thead> <tbody> <tr> <td>1 BF175D</td> <td>BBSJ 1010001</td> <td>BBSJ 1011127</td> </tr> <tr> <td>2 BF200D</td> <td>BBRJ 1010322</td> <td>BBRJ 1015620</td> </tr> <tr> <td>3 BF200D</td> <td>BBRJ 8010038</td> <td>BBRJ 8011279</td> </tr> <tr> <td>4 BF225D</td> <td>BBPJ 1010234</td> <td>BBPJ 1014461</td> </tr> <tr> <td>5 BF225D</td> <td>BBPJ 8010153</td> <td>BBPJ 8012359</td> </tr> <tr> <td>6 BF250D</td> <td>BBNJ 1010220</td> <td>BBNJ 1023503</td> </tr> <tr> <td>7 BF250D</td> <td>BBNJ 8010058</td> <td>BBNJ 8014560</td> </tr> </tbody> </table>	Model	From	To	1 BF175D	BBSJ 1010001	BBSJ 1011127	2 BF200D	BBRJ 1010322	BBRJ 1015620	3 BF200D	BBRJ 8010038	BBRJ 8011279	4 BF225D	BBPJ 1010234	BBPJ 1014461	5 BF225D	BBPJ 8010153	BBPJ 8012359	6 BF250D	BBNJ 1010220	BBNJ 1023503	7 BF250D	BBNJ 8010058	BBNJ 8014560
Model	From	To																							
1 BF175D	BBSJ 1010001	BBSJ 1011127																							
2 BF200D	BBRJ 1010322	BBRJ 1015620																							
3 BF200D	BBRJ 8010038	BBRJ 8011279																							
4 BF225D	BBPJ 1010234	BBPJ 1014461																							
5 BF225D	BBPJ 8010153	BBPJ 8012359																							
6 BF250D	BBNJ 1010220	BBNJ 1023503																							
7 BF250D	BBNJ 8010058	BBNJ 8014560																							
Product Description	A grey and black marine outboard engine used for propelling boats.																								
Country of Origin	Japan																								
Counterfeit	No																								
Risk Level	Not provided																								
Risk Type	Injuries																								
Risk Description	<p>The affected products present a risk of injuries as it has been identified that the actuator link rod may break during use due to a lack of durability. This can then result in a loss of shift operation, leading to a potential loss of control of the vessel.</p> <p>The product does not meet the requirements of the Recreational Craft Regulations 2017.</p>																								
Corrective Measures	<p>The product has been recalled from end users. Affected dealers have been informed. Honda will also contact registered end users to arrange an appointment with their local Honda dealer to have their outboard engine repaired at no cost.</p> <p>If you need help locating a dealer, please access: https://www.honda.co.uk/marine/dealer-search.html#search</p>																								
Online Marketplace	N/A																								
Notifier	Local Authority Trading Standards																								