



<b>ACROHOME Telescopic Ladders</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>PSD Number</b>	2406-0065
<b>Product Type</b>	Other – Telescopic Ladders
<b>Product Identifiers</b>	See Annex for list of affected models.
<b>Product Description</b>	A variety of telescopic ladders in different sizes. Some have hooks added to the top or the side of the ladder for additional grip.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	Unsure
<b>Risk Level</b>	Serious
<b>Risk Type</b>	Injuries
<b>Risk Description</b>	<p>These products present serious risks of injuries as they failed strength testing for the limits recommended on the products themselves. The ladders pose the risk of bending due to repeated use whilst the user is attempting to retrieve a heavy load. This means that if the ladders were to collapse while in use, the user could fall and receive serious injuries.</p> <p>These products do not meet the requirements of the General Product Safety Regulations 2005.</p>
<b>Corrective Measures</b>	The import has been rejected at the border.
<b>Online Marketplace</b>	Amazon – The listing has been removed by the online marketplace.
<b>Notifier</b>	Local Authority Trading Standards



## Annex A – List of Affected Models

Product Name	Barcode	FBA Number	ASIN Number
4.9M Telescopic ladder, MF-TLA490	X001VKGZZ	FBA15HY7KM8CU239	-
4.5M Telescopic Ladder, MF-TLA450	-	FBA15HY7KM8CU000496	B089Y4QPL6
3.8M Telescopic Ladder with Hooks	X001VKI9VX, X001VKKZ01	FBA15HY7GHFFU00450	B07CVTMK1
3.2M Telescopic Ladder with Hooks, MF-TLA320	X001VHIACB, X001VKI9TP	FBA15HY7HKRZV000327	-
2.9M Telescopic Ladder with Hooks, MF-TLA290	X001VKI9QX, X001VKIA85	FBA15HY7JJDPU000211	-
4.1M Telescopic Ladder with Hooks, MF-TLA410	X001VKHXUN	FBA15HY7GYVJU000271	B089Y8H94M
2.9M Telescopic Ladder, MF-TLA290	-	FBA15HY7GHFFU000050	B07CVTZVIB
2.6M Telescopic Ladder with Hooks, MF-TLA260	X001VKKY4D, X001VKKNT	FBA15HY7JJDPU000016	B07CVTJFW4