



<b>My Babiie Infant Carriers</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	<p>MBC50B MB250IDDGF MB250IBFHB MB250IBFQG MB200IDDLB MB200IBFBL MB500IDDOP</p> <p>MB200ISFGT MB200IBFBN MB200IDDDPP MB200IDDBP MB500IBFGB MB500IDDMR MB500IDDST</p>
<b>PSD Number</b>	2409-0014
<b>Product Type</b>	Childcare articles and children's equipment - Infant carrier
<b>Product Identifiers</b>	<p>Brand: MyBabiie</p> <p>Models: MBC50B, MB250IDDGF, MB250IBFHB, MB250IBFQG, MB200IDDLB, MB200IBFBL, MB500IDDOP, MB200ISFGT, MB200IBFBN, MB200IDDDPP, MB200IDDBP, MB500IBFGB, MB500IDDMR, MB500IDDST</p> <p>Affected batches: #00001084, #00001125, #00001217, #00001134, #00001135, #00001136, #00001181, #00001182, #00001183, #00001184, #00001185, #00001137 and #00001138</p>
<b>Product Description</b>	Various models and colours of infant carriers. Affected products were purchased between March 2023 and March 2024.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	No
<b>Risk Level</b>	Not provided
<b>Risk Type</b>	Injuries
<b>Risk Description</b>	<p>The product presents a risk of injuries as it has been identified that a gap may appear between the handle and the seat shell, usually on one side. In certain circumstances, the handle may become loose or detach on one side, causing the car seat to move unexpectedly.</p> <p>The affected products do not meet the requirements of the General Product Safety Regulations 2005.</p>
<b>Corrective Measures</b>	The product has been recalled from end users. Owners should stop using the handle to carry the seat immediately. For further information, including on how to register for a collection and modification to the product, please access the MyBabiie safety notice at the following link: <a href="https://mybabiie.com/pages/safety-notice">https://mybabiie.com/pages/safety-notice</a> . My Babiie can also be contacted at <a href="mailto:info@mybabiie.com">info@mybabiie.com</a>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards