

Product Recall

SIBA NH Fuse-Links of Size NH000	
Aspect	Details
Images	
PSD Number	2408-0206
Product Type	Electrical fuse link
Product Identifiers	Brand: SIBA • 20-000-13/35E1 - Purchased from April 2024 – Batch code 00413667 • 20-000-13/50A - Purchased from May 2024 – Batch code 00523660 • 20-000-13/63A - Purchased from June - July 2024 -Batch code 00516957 • 20-477-08/50A - Purchased from July 2024 – Batch code 00441310
Product Description	Metal electrical fuse link. Manufacture date March 2024-July 2024. Affected fuses can be identified by the production period, either by the calendar weeks on the label on the packaging (032024 to 112024) and/or the quarterly imprint on the fuse: 124=quarter 1 / 2024
Country of Origin	Germany
Counterfeit	No
Risk Level	Low
Risk Type	Injuries
Risk Description	The product has been identified by the manufacturer as presenting a risk of as the sand sealing cap may not seal correctly, which could cause the sand to leak during use in high-vibration environments. This can negatively influence the extinguishing behaviour of the fuse in the event of a short circuit. The product does not meet the requirements of the General Product Safety Regulations (2005).
Corrective Measures	The product has been recalled from end users by the manufacturer. Owners should stop using the product immediately and contact Europa's customer service team to arrange for a return to be made. Europa can be contacted at: • Telephone: 01582 692 448 • Email: custserv@europa-plc.com
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts