




<b>Martindale/Drummond Test Lamp MTL10/15/20/20B Mk3</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>PSD Number</b>	2410-0004
<b>Product Type</b>	Hand tools – Test lamp
<b>Product Identifiers</b>	Brand: Martindale/Drummond Sales period: The affected products were sold from 2023 onwards. Please refer to Annex A on page 2 for full details on the affected products
<b>Product Description</b>	Various models of the Martindale / Drummond MTL10 / 15 / 20 / 20B Mk3.
<b>Country of Origin</b>	Philippines
<b>Counterfeit</b>	No
<b>Risk Level</b>	Not provided
<b>Risk Type</b>	Electric shock
<b>Risk Description</b>	<p>The affected models present a risk of electric shock because of an intermittent indication fault.</p> <p>The intermittent fault could have serious safety implications if the product is used to prove circuits are dead, and lead to electric shocks.</p> <p>This product does not meet the requirements of the General Product Safety Regulations 2005.</p>
<b>Corrective Measures</b>	<p>The product has been recalled from end users.</p> <p>Consumers are advised to immediately stop using the unit if the serial number falls within the affected range. Units with S/No 321xxxxxx and higher are not subject to recall. Contact Martindale Electric support for advice on 01923 441717.</p> <p>For more information on the recall please access further details on the Tester site at: <a href="https://www.testers.co.uk/blog/electrical/product-recall-martindale-drummond-mtl10-15-20-20b-mk3/">https://www.testers.co.uk/blog/electrical/product-recall-martindale-drummond-mtl10-15-20-20b-mk3/</a></p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards



## Annex A – Affected models

Product name	Product code
MTL10 S	No 309xxxxxxx-317xxxxxxx
MTL15 S	No 309xxxxxxx-315xxxxxxx
MTL20 S	No 313xxxxxxx-314xxxxxxx
MTL20B S	No 314xxxxxxx