




<b>Gazelle Bloom C7 pedal bike and Gazelle Bloom e-bike type C7 HMS or C380 HMS</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>PSD Number</b>	2410-0125
<b>Product Type</b>	Hobby / sports equipment - Bicycle and eBike
<b>Product Identifiers</b>	Brand: Gazelle Affected products: Gazelle Bloom C7, Gazelle Bloom e-bike C7 HMS or C380 HMS Production period of affected bikes and e-bikes: 15 August 2022 to 13 September 2024
<b>Product Description</b>	Two wheeled bicycles, one is a pedal bicycle and the other is a battery powered e-bike.
<b>Country of Origin</b>	Netherlands
<b>Counterfeit</b>	No
<b>Risk Level</b>	High
<b>Risk Type</b>	Injuries
<b>Risk Description</b>	<p>The product presents a high risk of injuries as it has been identified that the top bolt of the front carrier can come loose which can cause the carrier to suddenly block the front wheel whilst in use. This may result in the bicycle coming to sudden stop, potentially resulting in a falling hazard or injury.</p> <p>The products do not meet the requirements of the General Product Safety Regulations 2005 (pedal cycle), or the Supply of Machinery (Safety) Regulations 2008 (e-bike).</p>
<b>Corrective Measures</b>	<p>Gazelle have initiated a modification programme for the affected bicycles and e-bikes. Affected consumer are advised to make an appointment at their Gazelle bike store where a Gazelle specialist can provide an additional reinforcement to the front carrier.</p> <p>For further details, or to check if your frame number is included in the service action, please access the Gazelle notice at the following link: <a href="https://www.gazellebikes.com/en-gb/service-bloom">https://www.gazellebikes.com/en-gb/service-bloom</a></p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Office for Product Safety and Standards