




<b>Philips Pressurized Steam Generator Iron</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>PSD Number</b>	2411-0072
<b>Product Type</b>	Electrical appliances and equipment – Pressurized Steam Generator Iron
<b>Product Identifiers</b>	Brand: Philips Model numbers starting with: GC96 and PSG8 Batch numbers: 2421, 2422 and 2423
<b>Product Description</b>	A steam iron with 2 component parts, an iron part and a steam generator available in several colours.
<b>Country of Origin</b>	Indonesia
<b>Counterfeit</b>	No
<b>Risk Level</b>	Medium
<b>Risk Type</b>	Burns
<b>Risk Description</b>	<p>The product presents a risk of burns to the user as it has been identified that the welding seam of the boiler can split open.</p> <p>The failure of the welding seam leads to the escape of hot steam which can burn the user.</p> <p>The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.</p>
<b>Corrective Measures</b>	<p>The product has been recalled from end users.</p> <p>A modification programme is underway for repairs and refunds.</p> <p>For further information, access the Philips recall page at the following link: <a href="https://www.philips.co.uk/c-e/ho/recall-perfectcare-8000-9000-elite-series.html">https://www.philips.co.uk/c-e/ho/recall-perfectcare-8000-9000-elite-series.html</a></p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards