




<b>3M™ Scott™ ELSA, Munster, Emergency Life Support Apparatus</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>PSD Number</b>	2411-0159
<b>Product Type</b>	Emergency Life Support Apparatus
<b>Product Identifiers</b>	2007116 ELSA MUSTER 15 MIN AS WITH HOOD EMPTY A list of part numbers, descriptions and codes is included at Annex A.
<b>Product Description</b>	The 3M™ Scott™ ELSA (Emergency Life Support Apparatus) muster variant, is an escape breathing apparatus which provides a constant supply of air for rapid escape from hazardous industrial and marine environments. It is supplied with a portable compressed air cylinder should the air become unbreathable. A fully charged air cylinder would provide the user with at least 15 minutes of breathable air to leave the hazardous area.
<b>Country of Origin</b>	United Kingdom
<b>Counterfeit</b>	No
<b>Risk Level</b>	Low
<b>Risk Type</b>	Respiratory
<b>Risk Description</b>	<p>3M™ Scott™ Fire &amp; Safety has identified a quality issue involving a limited quantity of certain batches of hood assemblies on the 3M™ Scott™ ELSA 2000, Sprint &amp; Muster variants. A limited number of ELSA Hood assemblies have been identified with a seam defect that may cause air to leak from the hood and contaminants from the external environment to flow into the hood.</p> <p>The affected part numbers were supplied between the 29th of June 2023 and the 30th of May 2024</p> <p>3M confirm that there have been no reports of injuries or accidents associated with this notice.</p>
<b>Corrective Measures</b>	The product has been recalled from end users.  3M has posted a customer advisory notice on their website, for customers and authorised distributors <a href="#">3m-psd-scba-elsa-notification-july-2024.pdf</a> advising them to return any defective products to their nearest 3M Scott Authorised Service Centre.
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Health and Safety Executive

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <https://www.gov.uk/guidance/product-recalls-and-alerts>



## Annex A – Product Identifiers

Where the ELSA hood has a printed code (e.g. FXXXXX) on its inside edge:

F30241
F30242
F30244
F30245
F30246
F30247
F30248
F30249
F30251
F30239