




Lamona Heat Pump Tumble Dryer	
Aspect	Details
PSD Number	2505-0141
Product Type	Electrical appliances and equipment – Heat Pump Tumble Dryer
Product Identifiers	<p>Affected Models:</p> <ul style="list-style-type: none">• LAM8876• LAM8877• LAM8878• LAM8879 <p>The model and serial number can be found on the right-hand side of the appliance upon opening the door (see image).</p> 
Product Description	<p>Lamona-branded built-in heat pump tumble dryer.</p> <p>Owners can check whether they have an affected product by checking their model number and serial number and following the instructions in the manufacturers' websites.</p>
Country of Origin	Turkey
Counterfeit	No
Risk Type	Fire
Risk Description	<p>The products present a risk of fire as it is possible for an internal short circuit to occur within the tumble dryer during normal use. This can cause the tumble dryer to ignite, causing a fire.</p> <p>The products do not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.</p>
Corrective Measures	<p>The manufacturer has initiated a modification programme.</p> <p>Owners are strongly advised to STOP USING THE PRODUCT IMMEDIATELY and contact the manufacturer to arrange for a modification to take place. The product should not be used until the modification has taken place. If the plug is accessible, switch off and unplug the appliance.</p> <p>For further information, access the Lamona product safety notice: Product Safety Notices and Recalls Aftersales Howdens</p> <p>To check if your product is affected, please visit https://productsafety-lamona.haier.co.uk/customer</p>
Online Marketplace	N/A



Office for Product
Safety & Standards

Product Safety Report

Notifier	Office for Product Safety and Standards
----------	---