




Product Safety Report

| Travel Iron | |
|---------------------|---|
| Aspect | Details |
| Images |  |
| PSD Number | 2509-0196 |
| Product Type | Electrical appliances and equipment - Ironing Boards (Powered) |
| Product Identifiers | Model: HT-258B Product identifiers: B040000000129702 0353, M010000000006472354, WI43895358, No 9. |
| Product Description | A travel iron with wall plug attached. |
| Country of Origin | China |
| Counterfeit | Unknown |
| Risk Level | Serious |
| Risk Type | Fire |
| Risk Description | <p>The product presents a serious risk of fire as the fuse does not meet the dimensional requirements of BS 1362. This means that under fault conditions, the fuse may fail to prevent fire and/or explosion.</p> <p>The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs and Sockets (Safety) Regulations 1994.</p> |
| Corrective Measures | The import has been rejected at the border |
| Online Marketplace | N/A |
| Notifier | Local Authority Trading Standards |