

NOTICE OF AUTHORIZED AMENDMENT: MAA/NAA/21/72

RA(s) or Manual Chapter(s):	RA 5305 and RA 5405
RFC Reference(s):	MAA/RFC/2021/015, 2021/035, 2021/104, 2021/123
NPA Reference(s):	NPA 21/37

	Post	Rank/Name	Date
MAA Author	MAA-Reg-Eng-5000	Redacted	02 Dec 21
MAA Supervisor	MAA-Reg-Eng	Redacted	02 Dec 21
MAA Independent	MAA-Reg-Eng-1000	Redacted	02 Dec 21
MAA LegAd (if required)	N/A	N/A	N/A

Amendment Classification (iaw MAA SOP 20)	Minor Change	Publishing Requirements:	Next regular release
--	---------------------	--------------------------	----------------------

Cross-references to Other Documents or Relevant Sources	
Other MRP Amendments	N/A
Service Inquiry Recommendations	N/A
AAIB Recommendations	N/A
Other Investigation Recommendations	N/A
Any Other Document	N/A

Authorized Amendment
Summary/Overview of the amendment to explain/ensure that the reader understands: the rationale for the amendment; the major changes; and, importantly, the full context (including desired outcome) of the amendment.
The Regulated Community is reminded to check this amendment against any applicable AAMC, Waivers or Exemptions to ensure their ongoing validity.
Integration of RFCs and improve coherency and consistency of terminology. RA5305 – Additional requirement to pass draft MLs to DAPS who will assess any impact to Air System operations. RA5405 – Clarify amended SI(T) numbering convention. Ensuring part(s) supply is available for SI(T) completion.

ISSUE STATE CHANGES (if more lines required, contact the MRP Team)			
<i>Document Title</i>	<i>Previous Issue</i>	<i>New Issue</i>	
RA 5305 – In-Service Design Changes	Issue 5	To	Issue 6

RA 5405 – Special Instructions (Technical)	Issue 6	To	Issue 7
--	---------	----	---------

Approval (iaw MAA SOP 20)	Post	DSA-MAA-OpAssure-Eng-DepHd	
	Name	Redacted	
	Rank	Redacted	Redacted - Original Signed