



Department for  
Business, Energy  
& Industrial Strategy

Office for Product  
Safety & Standards

## Enforcement action taken in the period: 1 April 2016 to 30 September 2017

The Office for Product Safety and Standards was created in January 2018 by the Department for Business, Energy and Industrial Strategy, to enhance protections for consumers and the environment and drive increased productivity, growth and business confidence.

The Office takes forward the work of the previous Regulatory Delivery directorate, including its enforcement responsibilities. This list of statutory enforcement actions taken by Regulatory Delivery is being published as part of those responsibilities. The enforcement actions listed below were taken by Regulatory Delivery (RD) and any references to the regulator are under this name.

### May 2016

#### **Company:**

HUSKY RETAIL LIMITED

#### **Action taken:**

Enforcement undertaking accepted under:

Part 4 of Schedule 5 to the Ecodesign of Energy-Related Products Regulation 2010 AND

Part 3 of Schedule 4 to the Energy Information Regulations 2011

#### **Product:**

A domestic wine cooler

#### **Model:**

HUS-HM38-HY

#### **Breached regulation details:**

Regulation 14 (1) of the Ecodesign for Energy-Related Products Regulations 2010: The product failed to reach the prescribed Eco-design requirements of Annex II of Regulation 643/2009 AND

Regulation 11 (1) of the Energy Information Regulations 2011: failure to meet the responsibilities of a supplier under Regulation 7

#### **Detail:**

The product failed to reach the energy efficiency rating (A+) as declared on the energy label.

The energy label did not declare the rated capacity in standard wine bottles.

The declared volume of the product is different to the measured volume.

RD accepted an assurance from HUSKY RETAIL LIMITED that the product had been removed from sale and discontinued from the company's range. A completion certificate was issued.

**Company:**

JOHN GILLMAN & SONS (ELECTRICAL) LIMITED

**Action taken:**

Enforcement undertaking accepted under:

Part 4 of Schedule 5 to the Ecodesign of Energy-Related Products Regulation 2010 AND

Part 3 of Schedule 4 to the Energy Information Regulations 2011

**Product:**

Domestic fridge freezer

**Model:**

ICEKING-CH1040

**Breached regulation details:**

Regulation 14 (1) of the Ecodesign for Energy-Related Products Regulations 2010: The product failed to reach the prescribed Eco-design requirements of Annex II of Regulation 643/2009 AND

Regulation 11 (1) of the Energy Information Regulations 2011: failure to meet the responsibilities of a supplier under Regulation 7(1)(b)The product failed to meet the responsibilities of suppliers under 7 (1) (b)

**Detail:**

The product failed to reach the energy efficiency rating (A+) as declared on the energy label.

RD accepted an assurance from JOHN GILLMAN & SONS (ELECTRICAL) LIMITED that the product had been removed from sale and discontinued from the company's range. A completion certificate was issued.

June 2016

**Company:**

GROSVENOR TRADE KITCHENS LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A shipment of kitchen cabinets

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber used had been legally harvested.

GROVESNOR TRADE KITCHENS LIMITED has since been dissolved.

August 2016

**Company:**

NEPTUNE (EUROPE) LTD

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Kitchen island

**Breached regulation details:**

Regulation 4(c) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber used had been legally harvested. RD subsequently received written confirmation from NEPTUNE (EUROPE) LTD that it is now meeting the obligations of an operator.

**Company:**

POUNDLAND LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A shipment of wooden photo frames

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber used had been legally harvested.

RD has subsequently received written confirmation from POUNDLAND LIMITED that it is now meeting the obligations of an operator.

## September 2016

**Company:**

PERI LTD

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A shipment of plywood

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber used had been legally harvested.

RD has subsequently received written confirmation from PERI LTD that it is now meeting the obligations of an operator.

**Company:**

MERSEY TIMBER LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A shipment of decorative board (plywood)

**Breached regulation details:**

Regulation 4(c) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber used had been legally harvested.

RD has subsequently received written confirmation from MERSEY TIMBER LIMITED that it is now meeting the obligations of an operator.

**Company:**

THE FLOOR SHOP LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Plywood

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber used had been legally harvested.

RD has subsequently received written confirmation from THE FLOOR SHOP LIMITED that it is now meeting the obligations of an operator.

October 2016

**Company:**

PARAGON KITCHENS LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A shipment of kitchen units

**Breached regulation details:**

Regulation 4(c) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber used had been legally harvested.

RD has subsequently received written confirmation from PARAGON KITCHENS LIMITED that it is now meeting the obligations of an operator.

**Company:**

KONEXA KITCHENS LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A shipment of kitchen base units

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber used had been legally harvested.

RD has subsequently received written confirmation from KONEXA KITCHENS LIMITED that it is now meeting the obligations of an operator.

**Company:**

FINESSE FURNITURE LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A shipment of rosewood furniture

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber used had been legally harvested.

**Company:**

PROWOOD LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Sawn timber originating from Russia

**Breached regulation details:**

Regulation 4(c) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber had been legally harvested.

RD has subsequently received written confirmation from PROWOOD LIMITED that it is now meeting the obligations of an operator.

December 2016

**Company:**

RUSSIAN CELLULOSE COMPANY LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Sawn timber

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber had been legally harvested.

RD has subsequently received written confirmation from RUSSIAN CELLULOSE COMPANY LIMITED that it is now meeting the obligations of an operator.

**Company:**

CARMICHAEL INTERNATIONAL LTD

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Sawn timber

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber had been legally harvested.

RD has subsequently received written confirmation from CARMICHAEL INTERNATIONAL LTD that it is now meeting the obligations of an operator.

January 2017

**Company:**

SHAWFIELD TIMBER LTD

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Plywood

**Model:**

Plywood Poplar Core WBP glue

**Breached regulation details:**

Regulation 4(c) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber had been legally harvested.

RD has subsequently received written confirmation from SHAWFIELD TIMBER LTD that it is now meeting the obligations of an operator.

**Company:**

JTF WHOLESALE LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Outdoor furniture set

**Breached regulation details:**

Regulation 4(c) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber had been legally harvested.

RD has subsequently received written confirmation from JTF WHOLESALE LIMITED that it is now meeting the obligations of an operator.



February 2017

**Company:**

HEARTLANDS FURNITURE (WHOLESALE) LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

MDF furniture

**Breached regulation details:**

Regulation 4(c) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement sufficient measures to ensure the timber used had been legally harvested.

RD has subsequently received written confirmation from HEARTLANDS FURNITURE (WHOLESALE) LIMITED that it is now meeting the obligations of an operator.

May 2017

**Company:**

PENDENNIS SHIPYARD (HOLDINGS) LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

Teak Decking

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber used had been legally harvested. RD subsequently received written confirmation from PENDENNIS SHIPYARD (HOLDINGS) LIMITED that it is now meeting the obligations of an operator

**Company:**

STONES MARINE TIMBER LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

One shipment of teak

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Company failed to implement measures to ensure the timber used had been legally harvested. RD subsequently received written confirmation from STONES MARINE TIMBER LIMITED that it is now meeting the obligations of an operator.

July 2017

**Company:**

ERCOL FURNITURE LIMITED

**Action taken:**

Notice of Remedial Actions, issued under Regulation 11 of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Product:**

A wardrobe

**Breached regulation details:**

Regulation 4(b) of the Timber and Timber Products (Placing on the Market) Regulations 2013

**Detail:**

Ercol Furniture LIMITED failed to implement measures to ensure the timber used had been legally harvested. RD subsequently received written confirmation from Ercol Furniture LIMITED that it is now meeting the obligations of an operator.