

**No: 4/89**

**Ref: EW/G89/01/17**

**Category: 1c**

**Aircraft Type  
and Registration:**

Reims Cessna F152, G-BJVT

**No & Type of Engines:**

1 Lycoming O-235-L2C piston engine

**Year of Manufacture:**

1981

**Date and Time (UTC):**

10 January 1989 at 1535 hrs

**Location:**

Cambridge Aerodrome

**Type of Flight:**

Training

**Persons on Board:**

Crew - 1

Passengers - None

**Injuries:**

Crew - None

Passengers - N/A

**Nature of Damage:**

Relatively minor - to spar and wingtip

**Commander's Licence:**

Student Pilot

**Commander's Age:**

25 years

**Commander's Total  
Flying Experience:  
Information Source:**

23 hours (of which all were on type)

Aircraft Accident Report Form submitted by the pilot and further AAIB enquiries

The aircraft was being taxied between number 10 hangar on the left and another aircraft parked on the right. The left wing tip struck a notice board in front of the hangar causing relatively minor damage to the aircraft's left wing tip and structure.