

BULLETIN CORRECTION

| | |
|-------------------------------|--|
| AAIB File: | EW/C2007/07/02 |
| Wing: | Paramania Revolution 23 |
| Paramotor Unit: | Modified H & E Paramotors R120 series |
| Date & Time (UTC): | 8 July 2007 at 1950 hrs |
| Location: | Middle Barn Farm, Bexhill, East Sussex |
| Information Source: | AAIB Field Investigation |

AAIB Bulletin No 2/2009, page 119 refers

In the Section of the published account titled ‘**Examination of damaged aircraft**’ the sentence appears:

‘The lift arms attached to this paramotor unit were not those originally fitted to it by the manufacturer and these arms had then been further modified.’

Since that time further information has become available to the AAIB demonstrating that the arms were those originally fitted to this paramotor unit. The sentence should, therefore, read:

‘The lift arms attached to this paramotor unit were those originally fitted to it by the manufacturer and these arms had then been further modified.’