

AAIB Bulletin No: 12/94

Ref: EW/G94/09/11

Category: 1.1

Aircraft Type and Registration: DC-9-15, G-BMAC

No & Type of Engines: 2 Pratt & Whitney JT8D-7 turbofan engines

Year of Manufacture: 1966

Date & Time (UTC): 25 September 1994 at 1105 hrs

Location: Luton Airport

Type of Flight: Public Transport

Persons on Board: Crew - N/K Passengers - N/K

Injuries: Crew - None Passengers - None

Nature of Damage: Minor to right aileron

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: N/A

Commander's Flying Experience: N/A

Information Source: Aircraft Accident Report Form submitted by the pilot

While the crew and passengers were disembarking at the end of the flight, a catering/baggage truck struck the right aileron causing minor damage.