

INCIDENT

Aircraft Type and Registration: Boeing 737-436, G-DOCA
No & Type of Engines: 2 CFM 56-3-C1 turbofan engines
Year of Manufacture: 1991
Date & Time (UTC): 17 March 1995 at 0938 hrs
Location: Stand B7, London Heathrow Airport
Type of Flight: Public Transport
Persons on Board: Crew - 7 Passengers - 135
Injuries: Crew - None Passengers - None
Nature of Damage: Minor damage to left wingtip and logo light fairing; two static wicks broken; navigation light glass broken
Commander's Licence: Airline Transport Pilot's Licence
Commander's Age: 52 years
Commander's Flying Experience: 15,000 hours (of which 3,300 were on type)
Last 90 days - 174 hours
Last 28 days - 58 hours
Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft's left wingtip struck the top of a vehicle which was slightly over the safety line on Stand B7; the aircraft was correctly positioned. Both sustained only minor damage.