

No: 12/87

Ref: 1c

Aircraft type and registration: Gulfstream AA-5A G-PAWS

No & Type of engines: 1 Lycoming O-320-E2G piston engine

Year of Manufacture: 1979

Date and time (UTC): 30 September 1987 at 1008 hrs

Location: Blackbushe Airport, Camberley, Surrey

Type of flight: Training

Persons on board: Crew — 1 Passengers — None

Injuries: Crew — None Passengers — N/A

Nature of damage: Nose leg torque tube, propeller and shock load to the engine

Commander's Licence: Student Pilot

Commander's Age: "Over 18"

Commander's Total Flying Experience: 15 hours (all of which were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot.

During the landing from a 'first solo' circuit the aircraft bounced twice. On the second ground contact, the nose landing gear collapsed and the aircraft came to rest on the runway.