

ACCIDENT

Aircraft Type and Registration:	Beechcraft Baron B58, N27MW	
No & Type of Engines:	2 Continental IO-520-C piston engines	
Year of Manufacture:	1978	
Date & Time (UTC):	26 September 2009 at 1304 hrs	
Location:	Runway 09, Guernsey Airport, Guernsey	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - 1
Injuries:	Crew - None	Passengers - None
Nature of Damage:	Damage to landing gear, engines and propellers	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	45 years	
Commander's Flying Experience:	428 hours (of which 13 were on type) Last 90 days - 50 hours Last 28 days - 11 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

Whilst performing a touch-and-go on Runway 09 at Guernsey, the landing gear was inadvertently retracted instead of the flaps.