

Aircraft Type and Registration: Cessna F150L, G-BAIP

No & Type of Engines: 1 Continental O-200-A piston engine

Year of Manufacture: 1973

Date & Time (UTC): 30 May 1995 at 1330 hrs

Location: Beverley Airfield, Humberside

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Aircraft destroyed

Commander's Licence: Private Pilot's Licence

Commander's Age: 58 years

Commander's Flying Experience: 127 hours (of which 116 were on type)
Last 90 days - 14 hours
Last 28 days - 10 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

The wind was 300°/5 kt and the pilot was landing on Runway 30. The landing was very heavy and resulted in a collapsed nose landing gear, a buckled fuselage and extensive other damage. The pilot states that she can give no reason for this accident.