

FORMAL REPORT CORRECTION

AAIB File:	EW/C2009/02/02
Aircraft Types and Registrations:	Grob 115E Tutor, G-BYUT and Grob 115E Tutor, G-BYVN
Date & Time (UTC):	11 February 2009 at 1047 hrs
Location:	Near Porthcawl, South Wales
Information Source:	Formal Investigation

Aircraft Accident Report 6/2010, pages ix and 28 refer:

This report was amended with the following corrections on the AAIB website on 18 May 2011.

Page ix – GLOSSARY OF ABBREVIATIONS USED IN THIS REPORT

ARCC Area Rescue Co-ordination Centre should read:

ARCC **Aeronautical** Rescue Co-ordination Centre.

Page 28, under heading 1.15.1.1 Satellite based alerting system

In the second paragraph,

Area Rescue Co-ordination Centre (ARCC) should read **Aeronautical** Rescue Co-ordination Centre (ARCC).