

Piper PA-28-180, G-AVNP

AAIB Bulletin No: 6/99 Ref: EW/G99/03/29 Category: 1.3

Aircraft Type and Registration: Piper PA-28-180, G-AVNP

No & Type of Engines: 1 Lycoming O-360-A4A piston engine

Year of Manufacture: 1967

Date & Time (UTC): 27 March 1999 at 1215 hrs

Location: Shipdham Airfield, Norfolk

Type of Flight: Private

Persons on Board: Crew - 1 - Passengers - 1

Injuries: Crew - None - Passengers - None

Nature of Damage: Slight to propeller

Commander's Licence: Private Pilot's Licence

Commander's Age: 49 years

Commander's Flying Experience: 90 hours (of which 81 were on type)
Last 90 days - 15 hours
Last 28 days - 12 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

The pilot had departed from Southend and was landing at Shipdham. On landing, the aircraft bounced twice and the pilot elected to execute a go-around and return to Southend. Post flight inspection revealed slight damage to the propeller.