

No: 4/89

Ref: EW/G89/02/03

Category: 1c

**Aircraft Type
and Registration:**

Piper PA-30CR, G-CALV

No & Type of Engines:

2 Lycoming IO-320-BIA piston engines

Year of Manufacture:

1969

Date and Time (UTC):

16 February 1989 at 1208 hrs

Location:

Kiddlington Aerodrome, Oxford

Type of Flight:

Private (Pleasure)

Persons on Board:

Crew - 1 Passengers - 1

Injuries:

Crew - None Passengers - None

Nature of Damage:

Damage to the landing gear, left wing and propellers

Commander's Licence

Private Pilot's Licence with Instrument and Night Ratings

Commander's Age:

33 years

**Commander's Total
Flying Experience:**

728 hours (of which 7 were on type)

Information Source:

Aircraft Accident Report Form submitted by the pilot

Following a normal landing on runway 27, the pilot decided to raise the flap during the landing roll. However, he operated the landing gear selector by mistake which caused the landing gear to collapse. The aircraft came to a halt on the lefthand side of the runway, and the occupants vacated it without injury.