

BULLETIN CORRECTION

AAIB File:	EW/G2008/05/25
Aircraft Type and Registration:	Piper PA-22-160 Tri-Pacer, G-ARDT
Date & Time (UTC):	18 May 2008 at 1230 hrs
Location:	Northside, 5 miles SW of Aberdeen
Information Source:	Aircraft Accident Report Form

AAIB Bulletin No 8/2008, page 111 refers

In describing the landing strip at Northside, the AAIB report on the accident stated that:

‘The centre and southern portions of the strip sloped upwards towards the south at an angle of about 25° to the horizontal.’

It should have stated that the centre and southern portions of the strip sloped upwards towards the south at an angle of about 6° to the horizontal.