ACCIDENT

Aircraft Type and Registration: Yakolev YAK-18T, G-VYAK

No & Type of Engines: 1 Ivchenko Vedeneyev M-14P piston engine

Year of Manufacture: 1993 (Serial No: 01-32)

Date & Time (UTC): 24 July 2012 at 1600 hrs

Location: Popham Airfield, Hampshire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Propeller destroyed, minor damage to wing trailing edge

and flaps

Commander's Licence: Air Transport Pilot's Licence

Commander's Age: 52 years

Commander's Flying Experience: 16,954 hours (of which 146 were on type)

Last 90 days - 235 hours Last 28 days - 54 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

The pilot intended to fly a number of visual circuits at Popham. The weather was fine, with light winds and good visibility. Runway 21 was in use, which was a 900 m long grass runway.

Whilst turning downwind for a touch-and-go, the pilot heard a transmission to a joining aircraft that there were two aircraft in the circuit. He thought that his aircraft was the only one in the circuit at that time (another had recently departed), but commenced a visual search for another. He could not see one, but noted three aircraft at the runway holding point awaiting departure. Two

of these took off as his aircraft turned finals. The pilot selected landing flaps but forgot to lower the landing gear. The aircraft settled onto the grass runway and slid to a stop. The pilot secured the aircraft, made a radio transmission to the effect that he was uninjured and vacated without difficulty.

The pilot considered that he had allowed himself to become distracted by the search for other circuit traffic and monitoring aircraft lining up and taking off ahead and that this had led to his omission to lower the landing gear.

© Crown copyright 2012