

Jodel DR105A, G-AXLS

AAIB Bulletin No: 9/99 Ref: EW/G99/07/15 Category: 1.3

Aircraft Type and Registration: Jodel DR105A, G-AXLS

No & Type of Engines: 1 Continental O-200-A piston engine

Year of Manufacture: 1959

Date & Time (UTC): 10 July 1999 at 1505 hrs

Location: Manor Farm, Wiltshire

Type of Flight: Private

Persons on Board: Crew - 1 - Passengers - 1

Injuries: Crew - None - Passengers - None

Nature of Damage: Damage to right wing, fuselage and tail. Parked Cessna 182 also sustained damage

Commander's Licence: Private Pilot's Licence

Commander's Age: 26 years

Commander's Flying Experience: 105 hours (of which 33 were on type)

Last 90 days - 26 hours

Last 28 days - 5 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

After a local flight, the pilot made an approach to Runway 10 at a private airstrip; the runway has a grass surface and is 645 metres long. The weather was good with an estimated surface wind of 030°/7 to 10 kt. The pilot reported that the aircraft landed heavily, bounced and veered to the right before turning back to the left; G-AXSL collided with one of several aircraft parked at right angles and to the right of the landing area.