

ACCIDENT

Aircraft Type and Registration:	Piper PA-28-140 Cherokee, G-BCJN	
No & Type of Engines:	1 Lycoming O-320-E3D piston engine	
Year of Manufacture:	1974 (Serial no: 28-7425350)	
Date & Time (UTC):	7 September 2015 at 1339 hrs	
Location:	Cotswold Airport, Gloucestershire	
Type of Flight:	Training	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to propeller and engine mounts, engine possibly shock-loaded	
Commander's Licence:	Student	
Commander's Age:	18 years	
Commander's Flying Experience:	32 hours (32 were on type, and less than 1 hour was PIC) Last 90 days - 15 hours Last 28 days - 15 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The aircraft, which was being flown solo by the student pilot, landed heavily, bounced and the propeller struck the runway. The aircraft then veered to the right, departed the runway and came to a stop on the grass.