

ACCIDENT

Aircraft Type and Registration:	Eurofox 912(S), G-CHUP	
No & Type of Engines:	1 Rotax 912ULS piston engine	
Year of Manufacture:	2013 (Serial no: LAA 376-15188)	
Date & Time (UTC):	31 March 2016 at 1301 hrs	
Location:	Shobdon Airfield, Herefordshire	
Type of Flight:	Private	
Persons on Board:	Crew - 2	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Right landing gear leg	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	82 years	
Commander's Flying Experience:	3842 hours (of which 22 were on type) Last 90 days - 6 hours Last 28 days - 15 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

Whilst landing on Runway 27 at Shobdon Airfield, the pilot reported that the right main landing gear leg failed as the aircraft turned off the runway to the left at slow speed. He believed the failure was due to damage that had resulted from a previous accident on 2 September 2014 (AAIB report EW/G2014/09/02 refers).