ACCIDENT

Aircraft Type and Registration: EV-97 Teameurostar UK, G-SHMI

No & Type of Engines: 1 Rotax 912-UL piston engine

Year of Manufacture: 2007 (Serial no: 3013)

Date & Time (UTC): 25 June 2016 at 1218 hrs

Location: Croft Farm Airfield, Defford, Worcestershire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Damage to right wing, landing gear, canopy and

propeller

Commander's Licence: National Private Pilot's Licence

Commander's Age: 65 years

Commander's Flying Experience: 129 hours (of which all were on type)

Last 90 days - 9 hours Last 28 days - 1 hour

Information Source: Aircraft Accident Report Form submitted by the

pilot and additional enquiries made by the AAIB

The pilot's final approach to Runway 28 at Croft Farm was witnessed by the ground radio operator. He stated that the aircraft appeared lower than he would normally expect to see similar aircraft on finals. Subsequently, the aircraft clipped a field of crop approximately 60 ft before the runway's threshold, impacted the ground and slid a further 50 ft before coming to a halt. Both occupants were able to vacate the aircraft without difficulty or injury. The pilot attributed the accident to his misjudgement of the aircraft's height on finals.

© Crown copyright 2016 57