

Grey shading = on-unit assessment made	FGW	NXEC	EMT	XC	NXEA Mk3	
Seat back handles	Y	Y	Y – contrast in standard could be better.	Y	Y – poor contrast	
Priority seats (inc move items)	Seats in 1 <sup>st</sup> need folding tables	Y	No priority seats	Y	Present in approx half vehicles	
Priority seat labels	Y	Y (some missing)	N	Y	Y (some missing)	
Wheelchair spaces/train length	3 (one in 1 <sup>st</sup> not fully compliant)	3 (one in 1 <sup>st</sup> not fully compliant)	2 (one in each class) but not to modern standards	3	2 compliant in 1 <sup>st</sup> . 3 <sup>rd</sup> needed	
Call for aid button	Needed in one Std and 1 <sup>st</sup> space	In both Std but needed in 1st	N	?	Y	
Wheelchair companion seat (not mandatory)	Y	Y (not for 1 std)	Y		Y – only at one	
Door opening forces	Handles likely to be acceptable but drop-light forces excessive	Handles likely to be acceptable but drop-light forces excessive	Handles likely to be acceptable but drop-light forces excessive	Handles likely to be acceptable but drop-light forces excessive	Handles likely to be acceptable but drop-light forces excessive	
Floor contrast at doors	N/A – doors instead	N/A – doors instead	N/A – doors instead	N/A – doors instead	N/A – doors instead	
Door sounders (only enable required if remain unpowered)	N	N	N	N	N	
Door button height	n/a	n/a	n/a	n/a	n/a	
Door button illumination	n/a	n/a	n/a	n/a	n/a	
Door obstacle detection	n/a	n/a	n/a	n/a	n/a	
Markings on glass	Y	Y - single marking at 1415 – 1555mm plus vent lower in door	Y - Vents in doors comply with RVAR09/TSI Other markings are patchy and at incorrect heights.		Y	
Step lights	N but no longer required	N but no longer required	N but no longer required	N but no longer required	N but no longer required	
Toilets (inc baby change)	UAT in Std only	UAT in Std only	Larger accessible type toilet in 1st only – but not to modern standards.	UAT in Std & 1 <sup>st</sup>	UAT in 1 <sup>st</sup> (no wheelchair spaces in Std)	
Minimum door width	External door width 840mm	External door width 840mm	External door width 840mm	External door width 840mm	External door width 840mm	
Wheelchair through way	Inadequate to 1 <sup>st</sup>	620mm to 1 <sup>st</sup> - inadequate	Restricted by standard internal door widths	Y	Y	
Customer information (PIS)	N	N	N	N	N	
Notices - tactile	Y	Y		Y	Y	
Handrails	Y –	Y –	Y –	Y	Y –	

	contrasting handrails but at wrong height	contrasting handrails but at wrong height	contrasting handrails but at wrong height		contrasting handrails but at wrong height	
Contrasting band on step	Y	Y	Y – but showing cleaning issues		Y – on outer step only. Showing cleaning issues	
Boarding aids (ramps)	Y – need fixing points	Y – need fixing points	Y – need fixing points	Y – need fixing points	Y – need fixing points	