Redacted

Redacted



Ref No: MAA/NAA/18/07

NOTIFICATION OF AUTHORIZED AMENDMENT (MAA-NAA- 18/07)

Document Set(s):		3000 Series: Air Traffic agement (ATM)	Regulatory Article(s)/Manual Chapter(s)	RA 3261 RA 3262 RA 1026
RFC Reference	MAA-RFC-2017-186 MAA-RFC-2017-012 MAA-RFC-2015-013		NPA Reference	NPA-18/07
Amendment Author		DSA-MAA-Reg- ATM2-ADInfra	Redacted	Redacted

Amendment Classification (As per MAA SOP 20 Matrix)	Routine (1*/OF5)	Publishing Requirements:	As soon as practicable

Redacted

Redacted

AUTHORIZED AMENDMENT

Amendment Supervisor

Amendment Independent

Note to provide a summary/overview of the amendment and to explain/ensure that the reader understands: the rationale for the amendment; the major changes; and, importantly, the full context (including desired outcome) of the amendment.

The input here should be your 'one minute' to explain what, why and how.

DSA-MAA-Reg-ATM

DSA-MAA-DepHd

This NAA covers amendments to the ATM MRP (RA 3261, RA 3262 and RA 1026) based upon changes to Standardised European Rules of the Air (SERA), an MAA review of aerodrome movement area and runway incursion reporting and a change in qualifications for aerodrome operators.

Amplification:

RA 3261 - Aerodrome Service. The most significant amendments cover:

- 1. RA 3261 Aerdrome Service. Creation of a new regulatory article RA 3261(3) to reflect Aerodrome Service/ATS in Class D airspace in line with Standarised European Rules of the Air (SERA). Existing AMC has been moved from RA 3261(1) and two additional sets of change marks have been included to highlight the new AMC for the 1500' cloud ceiling requirements and cancelling IFR flight.
- 2. RA 3262 Aerodrome Access has a revised Rationale to reflect Context, Hazard, Defence. The Regulation has been amended to reflect who is responsible for the the implementation of the regulation. AMC and GM now includes the requirement to brief the parameters for runway and aerodrome movement area incursions.
- 3. RA 1026 Aerodrome Operator. RA 1026(3) AO Qualification the requirement for course attendance at sub para 15a now subsumed into para 15. Requirement that stipulate a Branch specification at sub para 15b now relaxed and moved into GM at para 17.

Version 3 Page 1 of 2



Ref No: MAA/NAA/18/07

ISSUE STATE CHANGES (if more lines required, contact the MRP Team)						
Document Title	Previous Issue		New Issue			
RA 3261 - Aerodrome Service	Issue 5	То	Issue 6			
RA 3262 - Aerodrome Access	Initial Initial	То	Issue 2			
RA 1026 - Aerodrome Operator	Issue 3	То	Issue 4			

APPROVAL	Post	MAA-Reg-DepHd	
Approved by: (IAW MAA SOP 20 Matrix) Name Rank	Redacted	Original, non redacted, signed	
	Rank	Redacted	

Version 3 Page 2 of 2