Recommendation Status Report: Trailer runaway near Hope, Derbyshire

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of the recommendation(s), as reported to us, are described by the following categories:

Key to Recommendation Status

Open	Actions to address the recommendation are ongoing.
(replaces Progressing and Implementation On-going)	
impromontation on going/	

Closed	ORR consider the recommendation to have been taken into consideration by an end implementer and
(replaces Implemented, Implemented by alternative means, and Non- implementation)	evidence provided to show action taken or justification for no action taken.

Insufficient response:	The end implementer has not provided sufficient evidence that the recommendation has been taken into
	consideration, or if it has, the action proposed does not address the recommendation, or there is
	insufficient evidence to support no action being taken.

Superseded:	The recommendation has been superseded either by a newer recommendation or actions have		
	subsequently been taken by the end implementer that have superseded the recommendation.		

Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the		
	recommendation.		

RAIB concern over the way that an organisation has responded to a recommendation are indicated by one of the following:

Red – RAIB has concerns that no actions have been taken in response to a recommendation.

Blue – RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.

White – RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Recommendation Status Report



Report Title	Trailer runaway near Hope, Derbyshire	
Report Number	03/2018	
Date of Incident	28/05/2017	

Rec No.	Status	RAIB Concern	Recommendation	RAIB Summary of current status
03/2018/01	Closed - I	None		ORR has reported that Network Rail has reported that it has
			The intent of this recommendation is to prevent ad hoc measures being taken when it is necessary to recover rail mounted trolleys and trailers.	completed actions taken in response to this
				recommendation. ORR proposes
			Network Rail should provide clear instructions and training to users of rail	to take no further action unless
			mounted trolleys and trailers on its infrastructure, on the procedures to	they become aware that the
			be followed in the event of failures, such as of braking systems, that require them to be recovered (paragraph 98b).	information provided becomes inaccurate.
03/2018/02	Closed - I	None		ORR has reported that Network
			The intent of this recommendation is to confirm that the competence management of staff with safety critical roles is being effectively implemented.	Rail has reported that it has completed actions taken in response to this recommendation. ORR proposes to take no further action unless
			Network Rail should investigate the arrangements for the management of safety critical competencies at its Manchester Delivery Unit to understand the circumstances that led to the mismatch between the competence	they become aware that the information provided becomes inaccurate.
			records of individuals, the assessments they had undertaken and their	
			actual experience. Network Rail should consider whether these	
			circumstances could exist elsewhere and take appropriate actions against a time-bound plan (paragraph 99).	
03/2018/03	Closed - I	None	The intent of this recommendation is for Network Rail to improve levels of compliance with standards and codes of practice.	

Recommendation Status Report



Network Rail should take steps to understand the factors at its	
Manchester Delivery Unit that led to the non-compliances identified in	
this report, and implement the measures required to improve compliance	
with the relevant standards and codes of practice. Network Rail should	
also consider whether the lessons learnt are relevant with respect to	
other activities at its Manchester Delivery Unit and elsewhere (paragraph	
100).	