Record						Junction		Junction		Response	
ID	Call Date	Call Type	Category of Contact	Site Location	Sub Category	From	Road	То	Description	Туре	Closed Date
									"Various sections of the M25 in Essex from J28 to J30 there are		
									square brown coloured small sections of highway mostly in lane 2		
									and 3 often under the gantries which were not resurfaced during		
									improvements this very old surface has now broken up and deep		
				J28-30 road surface in lanes					potholes exist where the concrete substrate beneath is exposed. It is		
25453	26/10/2016 10:42	Enquiries	Road or Footway Surface	2 and 3 Contribution	Irregular surface (bumps dips)	28	M25	30	very alarming to hit these holes at 70mph"	E-Mail	02/11/2016 09:52
									Caller has called to state that the signage and lane markings on the		
									A13 approaching the M25 (westbound) are incorrect. He states that		
									on approach it is marked that the N/S lane is to go south and the		
									O/S lane is to go north. At the lights the N/S lane is one dedicated		
									lane to go south. The O/S lane splits into 3 lanes 1 going to M25		
									south and 2 going to M25 north. The caller states that the lines		
									need to be painted so that the lanes split evenly into both directions		
									(two north from the N/S lane and 2 south from the O/S lane). Caller		
26735	15/06/2017 09:57	Complaint	Road or Footway Surface		Road markings (studs and lines)	30	M25	30	has requested a response via email.	Telephone	27/06/2017 15:01
									Dear Sir/ Madam I have been advised by Thurrock Council to		
									contact yourselves as the slip road in question mentioned below is		
									under your jurisdiction. The slip road which comes off of the A13 at		
									Wennington (for A1306) travelling London bound is in a particularly		
									poor condition to the extent that it is starting to damage vehicles.		
									Large sections of the top of the road surface have eroded away with		
									a number of pot holes and ridges forming in the road. I have		
									attached a map from Thurrock Council to confirm where the issue is		
									(highlighted). I would be grateful if you could look at this as soon as		
23398	20/01/2016 09:34	Complaint	Road or Footway Surface	A13 - Poor road surface	Irregular surface (bumps dips)	A1306	A13		possible.	Telephone	27/01/2016 12:01
									Caller is complaining that on saturday 05/11/16 she was travelling		
									on the A13 with junction of A1306 towards london she hit a large		
									pothole which has caused her physical injury she has been tyring to		
									report this incident since then she feels that this is a serious		
25562	10/11/2016 12:13	Complaint	Road or Footway Surface	A13/A1306 pothole	Irregular surface (bumps dips)	A1306	A13		pothole/roadsurface	Telephone	25/11/2016 14:49