

BULLETIN CORRECTION

Aircraft Type and Registration:	Grumman AA-5 Traveller, G-BEZF
Date & Time (UTC):	2 September 2018 at 1020 hrs
Location:	Turweston Aerodrome, Buckinghamshire
Information Source:	Aircraft Accident Report Form submitted by the pilot

AAIB Bulletin No 3/2019, page 134 refers

There was a typographical error in the aircraft registration in the penultimate sentence in the first paragraph. The text should read:

Although the engine had stopped, the propeller was still rotating when G-BEZF struck the parked aircraft.

A new sentence was also added at the end of the report to provide additional information as follows:

The syndicate member subsequently reported that the aircraft maintainer found no faults when he checked the brakes and assessed that the 'feel' of the brake pedals was within normal experience.

The online version of this report was amended prior to publication.