Recommendation(s) Status: Near miss with a member of staff at Rowlands Castle station, Hampshire

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into eight categories:

Key to Recommendation Status

Open (replaces Progressing and Implementation On-going)	Actions to address the recommendation are ongoing.
Closed (replaces Implemented, Implemented by alternative means, and Non- implementation)	ORR consider the recommendation to have been taken into consideration by an end implementer and evidence provided to show action taken or justification for no action taken.
Insufficient response:	The end implementer has not provided sufficient evidence that the recommendation has been taken into consideration, or if it has, the action proposed does not address the recommendation, or there is insufficient evidence to support no action being taken.
Superseded:	The recommendation has been superseded either by a newer recommendation or actions have subsequently been taken by the end implementer that have superseded the recommendation.
Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the recommendation.

RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following:

Red – RAIB has concerns that no actions have been taken in response to a recommendation.

Blue – The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.

White – The white triangle shows recommendations where the RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Recommendation Status Report



Report Title	Near miss with a member of staff at Rowlands Castle station, Hampshire			
Report Number	06/2021			
Date of Incident	19/12/2020			

Rec No.	Status	RAIB Concern	Recommendation	RAIB Summary of current status
06/2021/01	Open	None	The intent of this recommendation is to ensure that new and existing	ORR has reported that
			MOMs are suitably recruited, trained and managed such that they have	(Dutyholder name) has a
			the technical and non-technical skills to manage their own and others'	proposed action plan and
			safety when on or near railway lines.	timescale for delivery to be taken in response to the
			Network Rail should build on its work so far in reviewing the role and	recommendation. ORR will advise
			competency framework of MOMs and other operational response staff, to	RAIB when actions to address this
			develop and implement bespoke programmes for selection, recruitment,	recommendation have been
			training, assessment and monitoring at both local and national levels,	completed.
			commensurate with the particular nature of such work (paragraph 109a).	
06/2021/02	Open	None	The intent of this recommendation is to support the competence	ORR has reported that
			management of MOMs through changes to operations management	(Dutyholder name) has a
			arrangements, complementing recommendation 1 above as well as	proposed action plan and
			extending recommendation 5 of RAIB's class investigation (paragraph 112	timescale for delivery to be taken
				in response to the
				recommendation. ORR will advise
			Network Rail should introduce measures across its routes and regions	RAIB when actions to address this
			aimed at ensuring that the management arrangements for operational	recommendation have been
			response staff result in full and correct implementation of the revised	completed.
			competency framework arising from recommendation 1 (paragraphs 109a	
			and 109b). These measures may include, but not be limited to, the	
			capacities and capabilities of operations managers, and/or the	
			organisational structure of line management for operational staff	

Recommendation Status Report



06/2021/03	Open	None	The intent of this recommendation is to reduce the probability of further	ORR has reported that
			impacts on operational safety caused by shortfalls in safety-related	(Dutyholder name) has a
			management resources in Network Rail's Wessex route.	proposed action plan and
				timescale for delivery to be taken
			Network Rail's Wessex route should review its operations management	in response to the
			function against the company's Health and Safety Management System to	recommendation. ORR will advise
			ensure that key safety posts are suitably covered to be more resilient to	RAIB when actions to address this
			any prolonged staff unavailability, and take steps to implement any	recommendation have been
			improvements identified (paragraph 109b).	completed.
06/2021/04	Open	None	The intent of this recommendation is to reduce the risk posed to	ORR has reported that
			passengers at stations from non-stopping trains by ensuring that warnings	(Dutyholder name) has a
			of their approach are made in a timely manner.	proposed action plan and
				timescale for delivery to be taken
			South Western Railway should take action to ensure the adequacy of	in response to the
			safety-related passenger announcements and passenger information	recommendation. ORR will advise
			display messages at all of its stations. In particular, warnings of	RAIB when actions to address this
			approaching non-stopping trains should be reviewed and, if necessary,	recommendation have been
			adjusted to ensure that they are made neither too early nor too late to be	completed.
			useful. The continued adequacy of such warnings should then be	
			confirmed as part of routine platform risk assessment processes	
			(paragraph 110b).	
			This recommendation may apply to other station operators and	
			infrastructure managers	