MARINE INFORMATION NOTE



MIN 649 (M) Amendment 1

Code of Safe Working Practices for Merchant Seafarers: Amendment 2020

Notice to all shipowners, ship operators and managers, masters and seafarers

This notice replaces MIN 601(M) and MIN 649(M). This MIN expires 30th November 2021

Summary

This Marine Information Note provides information about the 2020 amendments to the Code of Safe Working Practices for Merchant Seafarers ("the Code").

The Code covers the regulatory framework and provides best practice guidance for health and safety on board ship. It also gives guidance on safety management and identifies statutory duties underlying the advice and includes practical information for safe working on board.

Amendment 1 reflects editorial alterations only.

1. Introduction

- 1.1 An amendment to the Code of Safe Working Practices for Merchant Seafarers ("the Code") was issued on 26th November 2020 after consultation with industry.
- 1.2 The Code is an authoritative best practice manual on health and safety on board ships and is endorsed by the National Maritime Occupational Health and Safety Committee (NMOHSC). It deals with the regulatory framework for health and safety on board ship, safety management and statutory duties underlying the advice and gives practical information on safe working.

2. Amendments

- 2.1 The following table summarises the changes that have occurred in the 2019 4th Edition of the Code, following public consultation and review by the COSWP Working Group, which consists of representatives of the shipping industry, seafarers and seafarers' unions in collaboration with MCA policy leads.
- 2.2 In addition, in various chapters references have been updated and typographical corrections made.



Chapter	Title / Paragraph Number (old reference if altered)	Reason for 2020 Amendment	2020 Amendment Title / Paragraph Number
Chapter 4 - Emergency Drills and Procedures	New section and Annex	To add current guidance on Damage Control Drills and clarification of drills per vessel class	4.13 Damage Control Drills - New section Annex 4.1 Table of Emergency Drills and their Frequency
Chapter 5 - Fire Precautions	5.3 Electrical and other fittings	Stakeholder engagement comment	5.3.5 Amended wording
Chapter 6 – Security On Board	6.1 Introduction	Reference review	6.1.1 MCA's Wellbeing at Sea: A guide for organisations, Chapter 3.3, and Wellbeing at Sea: A pocket guide for seafarers, Chapter 2.5.
Chapter 9 - Safety Signs and their Use	9.1 Introduction	Chapter reviewed to reflect requirements of IMO Resolution A.1116(30)	9.1 Referencing9.1.1 Additional final sentence
Chapter 11 - Safe Movement Onboard Ship	11.5 Lighting	To reflect HSG38 – Lighting at Work and current guidance	11.5.2 Grammatical amendment
			11.5.3 Section reviewed Annex 11.2 Lux values and bullet points updated
Chapter 12 - Noise, Vibration and Other Physical Agents	12.1 General Advice	Chapter review in light of HSE Hand, Arm Vibration (HAV) Guidance 2019	12.1.1 Reference to MCA's Wellbeing at Sea: A guide for organisations, Chapter 3.7. 12.2.2 Bullet (1)
	12.2 Prevention or control of exposure to a physical agent		12.2.6 Amended wording
	12.12 Determining Vibration Levels		12.12.8 & 12.12.9 New sections relating to vibration exposure limit values (ELVs)
	12.14 Mitigation		12.14.7 Section reviewed.
	Annex 12.2 Daily Exposure to Different Sound Levels		Annex 12.2 Updated guidance to IMO Resolution MSC337(91) Code on Noise Levels onboard Ships
Chapter 15 - Entering Dangerous Spaces (Enclosed Spaces)	15.6 Testing the Atmosphere of the Space	Red Ensign Group Yacht meeting enquiry concerning SOLAS Chapter X1-1 – Portable Atmosphere Testers, as applicable to yachts.	15.6.5 Amended wording for guidance on monitoring equipment 15.6.6 New section reflecting guidance for smaller vessels.
	15.6.11 Testing for toxic gases	All sections reviewed to follow current guidance.	 15.6.12 Testing for toxic gases; Amended wording and includes adjustment for testing for specific contaminants 'such as benzene or hydrogen sulphide' 15.6.13 New summary section with table outlining the conditions to be tested as a minimum, following current limits within EH40 as of August 2020. https://www.hse.gov.uk/pubns/books/eh40.htm



	15.14 Preparation for an Emergency	Customer enquiry into the use of Emergency Escape Breathing Equipment (EEBD) when carrying out a rescue.	15.14.5 Amended wording to consider what rescue equipment is needed. 15.14.8 Amendment of section to clarify use of EEBD during a rescue. 15.14.9 New section; 'When entering a space to carry out a rescue, it is important to ensure that the area adjacent to the space of entry is free from any hazard and cordoned off accordingly'.
		to follow current guidance.	
Chapter 18 – Provision, Care and Use of Work Equipment	18.17 Portable power-operated tools and equipment	Stakeholder engagement comment	18.17.2 Amended section 18.17.3 Amended section 18.17.4 Amended section
Chapter 20 - Work on Machinery and Power Systems	20.2 General	To reflect current guidance and stakeholder engagement comments	20.2.4 Addition of 'prevented from' 20.2.8, 20.2.9 & 20.2.10 New sections to reflect requirements for the isolation of power sources
	20.9 Refrigeration machinery and refrigerated compartments		 20.9.1 Addition to sentence 'or having first completed a permit to work (PTW), as part of the risk assessment process.' 20.9.2 Addition to sentence 'and appropriate PPE should be worn when undertaking any task involving the handling of chemicals'.
	20.10 Steering Gear	Section reviewed to reflect the requirements of planned maintenance of 'critical equipment'.	20.10 New title - Critical equipment.
	20.11 Hydraulic and pneumatic equipment		20.11 Steering Gear – section reviewed 20.12 Hydraulic and pneumatic equipment
	20.12 Electrical Equipment 20.12.1	Lock Out Tag Out (LOTO) safety guidance	20.13 Electrical Equipment 20.13.1 Replaced word 'wetness' with 'moisture' Review of wording 'as low as 60V' to 'of 60V or lower' 20.13.3 New section - Lock out, tag out
	20.12.3	Stakeholder engagement comment	20.13.7 Addition of wording 'the energy source should be isolated and any residual energy dissipated first'. Addition of reference to LOTO. 20.13.8 new heading 'Other Precautions' Additional wording to section.
	20.12.6	Stakeholder engagement comment	20.13.10 Amendment to first bullet point 'electrically competent and trained in first aid'.
	20.14.2 Definitions	Amended to include LOTO	20.15.2 Definitions Addition of new definition - LOTO: Lock out, Tag Out
	20.14.12 Notices 20.15 Arc-flash Associated with	Section reviewed to reflect current	20.15.12 Addition of terminology (Tags) 20.16.3 Addition of 'partial-thickness' burns and NHS reference



	1	NII 10 0000	T
	high and low	NHS 2020 definitions	20.16.5 Addition of new section
	voltage equipment 20.16 Storage of	Stakeholder	20.17 Storage batteries; general
	Batteries: General		20.17 Storage batteries, general 20.17.1 Amended section to follow
	Datteries. Gerierai	engagement comment	manufacturer's instructions concerning battery
		Comment	storage.
Chapter 22 –	22.6 Portable and	Reviewed portable	22.6.4 Amended
Boarding	rope Ladders	rope ladder	22.6.5 Deleted
Arrangements	Tope Lauders	guidance	22.6.6 Deleted
Chapter 23 –	23.1 Health and	Reference review	MCA's Wellbeing at Sea: A guide for
Food	Hygiene	TROTOTOTIOG TOVIOW	organisations, Chapter 3.8.1 and Wellbeing at
Preparation and	Try glotto		Sea: A pocket guide for seafarers, Chapters 1.1
Handling in the			and 1.2.
Catering			
Department			
Chapter 24 –	24.8 Precautions	Stakeholder	24.8.1 Updated official number references
Hot Work	to be taken during	engagement	•
	electric arc	comment	
	welding		
Chapter 26 -	26.3 Making fast	Snapback zones –	26.3.1 Section reviewed with reference added
Anchoring,	and casting off	Nautilus	to the; Effective Mooring (2019, 4th edition)
Mooring and		Telegraph July	from the Oil Companies International Marine
Safe Towing		2019 outlining	Forum (OCIMF).
Operations		conflictions with	26.3.2 Additional final sentence 'Seafarers other
		advice between	than the mooring parties should keep clear of
		COSWP and	the mooring decks during mooring and
		MAIB's Safety	unmooring operations'.
		Digest 2019, Case	26.3.3 Added reference to Annex 26.1 of
		3	potential snapback zones for illustrative
			purposes.
			26.3.11 Additional wording added to the section.
			26.3.12 Additional final sentence to highlight the
			risks when warping a vessel along a berth.
	26.6 Safe mooring	Chapter review to	26.6.4 Amended section 'Passengers and
	of domestic	reflect the MAIB	supernumerary personnel must be kept clear of
	passenger craft	Reports into the	all mooring and unmooring operations and all
	and ships'	Tug <i>Millgarth</i> 27	personnel should keep clear of snap-back
	launches to quays	January 2019 and	zones'.
		the dredger Cherry Sand 28	Part of an ongoing section review, with an MGN to be issued outlining guidance, to be
		February 2019.	incorporated into the next COSWP amendment.
Appendix 1 -		Out of date or	To reflect new MCA wellbeing guidance:
Regulations,		incorrect	Wellbeing at Sea; A pocket Guide for Seafarers
Marine Notices		references	and
and Guidance		amended.	Wellbeing at Sea; A guide for organisations
Issued by the			2. 2 String at a cap, 1. garage for organications
MCA			
Appendix 2 -		Out of date or	Updated website references to latest guidance
Other Sources		incorrect	
of		references	
Information		amended.	
Appendix 3 –		Out of date or	Updated to the latest British Standard reference
Standards and		incorrect	numbers
Specifications		references	
referenced in		amended.	
this Code			



More Information

Seafarer Services Maritime and Coastguard Agency Bay 2/17 Spring Place 105 Commercial Road Southampton SO15 1EG

Tel: +44 (0) 203 8172250

e-mail: <u>seafarersafety@mcga.gov.uk</u>

Website Address: www.gov.uk/government/organisations/maritime-and-coastguard-agency

General Enquiries: infoline@mcga.gov.uk

Published: December 2020

Please note that all addresses and

telephone numbers are correct at time of publishing

© Crown Copyright 2020

Safer Lives, Safer Ships, Cleaner Seas

