

**BULLETIN CORRECTION**

<b>Aircraft Type and Registration:</b>	Grob G102 Astir CS, G-CJSK
<b>Date &amp; Time (UTC):</b>	23 June 2021 at 1337 hrs
<b>Location:</b>	Gibett Hill, Brentor, near Tavistock, Devon
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot

**AAIB Bulletin No 12/2021, page 40 refers**

Following publication it was noted that in the first and fourth paragraphs on the second page of this report the airfield was named as Bodmin. This should have read Brentor.

The text should read:

The pilot launched by winch from **Brentor Airfield** at 1250 hrs and climbed to an altitude of 4,100 ft for local soaring.

And:

The glider came to rest in an area of open ground approximately 1 nm NNE from **Brentor Airfield** in an inverted attitude (Figure 1).

The online version of this report was corrected on 15 December 2021.