



<b>KTM Radical Scooter</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2205-0228
<b>Product Type</b>	Hobby / sports equipment
<b>Product Identifiers</b>	Batch number: 3PW210023000, 3PW210023090
<b>Product Description</b>	Kick scooter with height-adjustable and foldable handlebars; withstands up to 100 kg
<b>Country of Origin</b>	Hong Kong
<b>Counterfeit</b>	No
<b>Risk Type</b>	Injuries
<b>Risk Description</b>	Internal quality inspections have determined deviations in the stability of the RADICAL SCOOTER. The pin, which secures the connection between the steering stem and running board does not meet specifications. This can lead to increased play in the steering stem and, in extreme cases, to a breakage at the connecting point to the running board.
<b>Corrective Measures</b>	The product has been recalled by end users
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Office for Product Safety and Standards