
PROPOSED MODIFICATIONS

Revised map MR1 showing minor modifications to the route, specifically the straightening of the route between sections S004-S007 to prevent the loss of landowners' land (as indicated on the map) and the installation of fencing landward between S005-S006 to mitigate the risk of contact with livestock at this pinch point (not shown on the map).



1	2	3	4	5a	5b	5c	6
Map(s)	Routes Section number(s)	Current status of route section(s)	Roll back proposed?	Proposals to specify seaward boundary of alternative route strip	Proposal to specify landward boundary of alternative route strip	Reason for landward boundary proposal	Explanatory notes
ABD 1a	ABD-1- S005*	Not an existing walked route	Yes - Normal	No	Fence line	Clarity and cohesion	
	ABD-1- S006*	Not an existing walked route	Yes - Normal		Fence line	Clarity and cohesion	