

NOTICE OF AUTHORIZED AMENDMENT: MAA/NAA/22/21

RA(s) or Manual Chapter(s):	MAM-P, Issue 2.4
RFC Reference(s):	N/A
NPA Reference(s):	N/A

MAA Author	Post	DSA-MAA-Reg-Eng-MAMDb	
	Name	Redacted	
	Rank	Redacted	Redacted - Original Signed

MAA Supervisor	Post	DSA-MAA-Reg-Eng-1200a	
	Name	Redacted	
	Rank	Redacted	Redacted - Original Signed

MAA Independent	Post	DSA-MAA-Reg-Eng-1200	
	Name	Redacted	
	Rank	Redacted	Redacted - Original Signed

MAA LegAd (if required)	Post	N/A	
	Name	N/A	
	Rank	N/A	Choose an item.

Amendment Classification (iaw MAA SOP 20)	Minor Change	Publishing Requirements:	ASAP
--	---------------------	--------------------------	------

Cross-references to Other Documents or Relevant Sources	
Other MRP Amendments	N/A
Service Inquiry Recommendations	N/A
AAIB Recommendations	N/A
Other Investigation Recommendations	N/A
Any Other Document	N/A

Authorized Amendment
Summary / Overview of the amendment to explain/ensure that the reader understands: the rationale for the amendment; the major changes; and, importantly, the full context (including desired outcome) of the amendment.
The Regulated Community is reminded to check this amendment against any applicable AAMC, Waivers or Exemptions to ensure their ongoing validity.
<p>All amendments agreed by the MAM-P Management Group and published by the MAA.</p> <p>Amendments included within this publication: Chapter 0.1 Table of Changes – Updated with current Chapter Issue versions and Dates. Chapter 0.4 Changes – Updated with current Chapter Issue versions and Dates. Chapter 4.10 - Updated to ensure the critical removal of parts from a serviceable component are correctly annotated on the MF731 and the item is conditioned correctly post part removal. Chapter 4.11 - Updated to ensure the originator raises Part A of the MF746D and the donor unit completes Part B of the MF746D (This is in line with what the instructions for users states on the Mod Form 764D). Chapter 4.13 - Updated email address to replace postal address of Operational Infrastructure – Safety, to make the process of tracking and submitting MF760 easier - DES LE OI-ENGR-SAFETY (MULTIUSER). Chapter 4.20 - Updated to align the MAM-P with changes to the Defence Aerodrome Manual – Static earth points are to be tested at regular intervals (at least annually) and power earth points to be tested every 24 months. Chapter 9.2 - Updated the addition of mandatory reporting of a faulty or defective Hand Tool to the list of occasions to raise a Narrative Fault Reporting Using the MOD Form 760 Series.</p>

ISSUE STATE CHANGES (if more lines required, contact the MRP Team)			
Document Title	Previous Issue	New Issue	
Chapter 0.1 Table of Contents	2.3	To	2.4
Chapter 0.4 Changes	2.3	To	2.4
Chapter 4.10 Technical Equipment – Conditioning and Preparation for Movement or Storage	1.4	To	2.4
Chapter 4.11 Cannibalization of Parts from Air Systems and Uninstalled Air System Equipment	2.1	To	2.4
Chapter 4.13 Management of Hand Tools and Test and Measuring Equipment	1.1	To	2.4
Chapter 4.20 Electrical Bonding and Earthing of Air Systems and Associated Airfield Support Equipment	1.2	To	2.4
Chapter 9.2 Narrative Fault Reporting Using the MOD Form 760 Series	Initial	To	2.4

Approval (iaw MAA SOP 20)	Post	DSA-MAA-Reg-Eng	
	Name	Redacted	
	Rank	Redacted	Redacted - Original Signed