

Please Quote P3505 - P3810 in all correspondence.

Offshore Petroleum Regulator DBEIS 3rd Floor AB1 Building (Wing C) Crimon Place Aberdeen AB10 1BJ

09/12/2022

Dear Sir / Madam,

Inspection of Local Aids to Navigation, Merchant Shipping Act, 1995, Section 198(1)

Please be advised that Trinity House is to inspect the aids to navigation on the offshore structures and wellheads.

Any structures positioned north of Latitude 55° 48'N in the North Sea will be inspected by the Northern Lighthouse Board for which separate arrangements will be made.

The West Coast Inspections will commence on or about 12th December 2022, and consist of viewing the aids to navigation from seaward, together with any special mark and wellhead marker buoys.

As with previous inspections, the Inspecting Officer will contact the platform control and monitoring station shortly before the inspection is to commence and will verbally advise, whenever possible, the inspection results on completion. In the event of a major defect that we are unable to advise the platform control or monitoring station of, you will be notified as soon as possible.

Upon completion of the inspections Trinity House will forward to you the results at the earliest opportunity.

Yours faithfully,

Kourufall

Rosemary Walsh | Local AtoN Advisor | Trinity House Direct Dial: 0207 481 6925 | Mobile : 07810757715 | Email: <u>seamarks@trinityhouse.co.uk</u>