

Product Safety Report

White Tycolit LED Panel Light, MA0108504	
Aspect	Details
Images	
Alert Number	2212-0213
Product Type	Electrical appliances and equipment – LED Panel light
Product Identifiers	Brand: Tycolit Model number: MA0108504
Product Description	Large square panel light
Country of Origin	China
Counterfeit	Unknown
Risk Type	Electric shock
Risk Level	Serious
Risk Description	The product presents a serious risk of electric shock as it is inadequately earthed and does not make the consumer aware in the instructions. If the product was to have a fault, there would be no earthing to stop it from becoming live, and without the consumer knowing, could give them an electric shock. The LED driver did not include an adequate means for anchoring the supply cord. The LED driver failed the electric strength test. It allowed a flashover when the 1250 V test voltage was applied between the input and earthed metal parts. Also, the appliance was inadequately earthed because the earth terminal had not been marked with the correct symbol, The clamping means was not adequately secured against accidental loosening, The contact surfaces were not of bare metal and the earth wire had an inadequate cross sectional area. The product is not accompanied by adequate instructions and safety information in a language easily understood by consumers and other end-users. The product does not comply with the Electrical Equipment (Safety) Regulations 2016
Corrective Measures	Import rejected at the border.
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts