

Product Recall

SCOTT Speedster Bicycle	
Aspect	Details
Images	Speedster 40 Speedster 50 Speedster Gravel 40 EQ Speedster Gravel 50 Contessa Speedster Gravel 35
Alert Number	2302-0023
Product Type	Hobby / sports equipment - Bicycle
Product Identifiers	Brand: SCOTT Model/type: 286437 Speedster 40 (EU) 286438 Speedster 50 (EU) 286442 Speedster 40 (CN) 286443 Speedster 50 (CN) 286472 Speedster Gravel 50 (CN) 286466 Speedster Gravel 50 (EU) 286471 Speedster Gravel 40 EQ (CN) 286465 Speedster Gravel 40 EQ (EU) 286490 Contessa Speedster Gravel 35 (EU) 286493 Contessa Speedster Gravel 35 (CN)
Product Description	A light and agile alloy road bike
Country of Origin	China
Counterfeit	Genuine
Risk Type	Injuries
Risk Level	Not specified – recall
Risk Description	The business has recalled these products due to a test identifying a crack in the fork steerer. This means that the fork steerer could break and cause an accident. Faulty forks can be replaced with a new fork free of cost at any SCOTT bike shop.
Corrective Measures	The products have been recalled from end users. For more information, please see: https://www.scott-sports.com/gb/en/company/safety-and-recalls
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts