



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

Our Reference:
FOI2022/08558
Date:
20 July 2022

Dear [REDACTED]

I am writing about your email of 14 July 2022, requesting the following information:

'I have recently purchased an ex mod land rover defender and i am writing to ask for any information you hold about its history etc,the military registration number was KA36AA and the chassis number is SALLDAA67VA111775 and it was delivered into service on the 08/10/1997'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

Annex A - Transfer History
Annex B - Inspection History
Annex C - Service History
Annex D - Modification History
Annex E - Fault History (redacted)

It has proved necessary to withhold some information in accordance with a qualified exemption of the FOI Act. Some of the information in the Fault History (Annex E) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, the Fault History provides details of the time taken by MOD contractors to rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Defence Equipment & Support

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KA36AA	2320998939741	NB42203100	LV2A/088AM3	TRUCK UTY LIGHT (TUL) (HS) 4X4 GS SOFT TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
08/10/1997	SALLDAA67VA111775	25L01144A	Y	28/11/2012

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KA36AA	3	07/10/1997	CA005A	JSCS ASHCHURCH	CAPITA	29315AA	08/10/1997	
KA36AA	4	12/11/1997	A1258A	1 PWRR	34907A	3738	09/12/1997	
KA36AA	4	29/11/1999	A0577A	1 R IRISH	116	653	03/12/1999	H/T
KA36AA	4	14/10/2002	A1650A	5 TRG REGT RLC STORE SECT	435	286	18/10/2002	T30
KA36AA	3	04/02/2013	CQ710A	WITHAM (SPECIALIST VEHICLES) LTD	999	999	04/02/2013	D10

[illegible]

[illegible]

[illegible]

Work Objects														
Serial Number:	KA3GAA													
NSN:	2320998939741													
Criteria:														
Repair Level:	ALL													
Work Object Status:	Closed													
Mission Impact:	ALL													
Fault State:	ALL													
Escalate Work:	ALL													
Work Request ID:														
Assigned Work Status:	ALL													
Working Organisation:														
Repair Section:														
Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-0072C6F1		WATER PUMP U/S	Closed	Non-Taskworthy	No	Level 2		02 Aug 2012	N/A	Failure	TUL HS GS SOFT TOP			000:00
000000-0071AD6A		NO LOWER RATIO OR DIFF LOCK	Closed	Non-Taskworthy	No	Level 2		07 Jun 2012	N/A	Failure	TUL HS GS SOFT TOP			
000000-007168AE		CARRY OUT 6 MTHLY L1 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 1		23 May 2012	N/A	Servicing	TUL HS GS SOFT TOP			
000000-007168C7		CARRY OUT 6 MTHLY L2 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 2		23 May 2012	N/A	Servicing	TUL HS GS SOFT TOP			
000000-00717279		PASSENGER WINDOW INOP	Closed	Fully Fit	No	Level 2		24 May 2012	N/A	Inspection	TUL HS GS SOFT TOP			
000000-0071726D		RHR SHOCK LOOSE	Closed	Fully Fit	No	Level 2		24 May 2012	N/A	Inspection	TUL HS GS SOFT TOP			
000000-00717268		TRANSFER BOX FRONT OUTPUT SEAL LEAKING	Closed	Fully Fit	No	Level 2		24 May 2012	N/A	Inspection	TUL HS GS SOFT TOP			
000000-007168A5		CARRY OUT AFB 6534 INSP	Closed	Non-Taskworthy	No	Level 1		23 May 2012	N/A	Inspection	TUL HS GS SOFT TOP			
000000-00707576		STARTER MOTOR KEEPS STICKING	Closed	Non-Taskworthy	No	Level 2		30 Mar 2012	N/A	Failure	TUL HS GS SOFT TOP			
000000-00707573		CLUTCH SLIPPING	Closed	Non-Taskworthy	No	Level 2		30 Mar 2012	N/A	Failure	TUL HS GS SOFT TOP			
000000-006FF5CC		BONNETT CATCH U/S	Closed	Non-Taskworthy	No	Level 2		12 Mar 2012	N/A	Failure	TUL HS GS SOFT TOP			000:00
000000-006E2FAA		RENEW BRAKE FLUID IAW AESP-2320-D-128-601 TABLE 5	Closed	Fully Fit	No	Level 2		01 Dec 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-006D13A1		RENEW ENGINE COOLANT IAW AESP-2320-D-128-601 TABLE 5	Closed	Non-Taskworthy	No	Level 1		07 Oct 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-006CF506		RENEW ENGINE OIL & FILTER IAW AESP-2320-D-128-601 TABLE 5	Closed	Non-Taskworthy	No	Level 1		08 Oct 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-006CF4DE		CARRY OUT 2 YRLY L1 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL C	Closed	Non-Taskworthy	No	Level 1		08 Oct 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-006CF4F0		CARRY OUT 2 YRLY L2 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL C	Closed	Non-Taskworthy	No	Level 2		08 Oct 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-006E2F97		CARRY OUT 2 YRLY L1 (REPEAT) TASKS IAW AESP-2320-D-128-601 TABLE 7 COL C	Closed	Non-Taskworthy	No	Level 1		01 Dec 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-006CF4F5		CARRY OUT AFG 932B MEI	Closed	Non-Taskworthy	No	Level 2		08 Oct 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-006E2F9A		CARRY OUT AFG 932B MEI RE-INSP	Closed	Non-Taskworthy	No	Level 2		01 Dec 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-006D388F		RENEW FRONT PANINARD ROD BUSHES	Closed	Fully Fit	No	Level 2		14 Oct 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-006D388A		RECTIFY OIL LEAK AT REAR OF T/BOX	Closed	Fully Fit	No	Level 2		14 Oct 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-006D3886		RECTIFY LEAK AT FRONT DIFF INPUT SEAL	Closed	Fully Fit	No	Level 2		14 Oct 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-006D388C		RECTIFY EXCESSIVE HANDBRAKE LEVER TRAVEL	Closed	Non-Taskworthy	No	Level 2		14 Oct 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-00680510		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-00000310	22 Jun 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-005F2B38		OIL LEAKS' ROCKER COVER	Closed	Fully Fit	No	Level 2		20 Apr 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-005F2B3A		FRONT DIFF INPUT SEAL LEAK	Closed	Fully Fit	No	Level 2		20 Apr 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-005F1AE3		CARRY OUT AFB 6534	Closed	Non-Taskworthy	No	Level 1		14 Apr 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-005F1889		RENEW AIR CLEANER ELEMENT IAW -AESP-2320-D-128-TABLE 5	Closed	Non-Taskworthy	No	Level 1		14 Apr 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-005F1ADF		CARRY OUT 6 MTHLY L1 TASKS IAW AESP2320-D-122-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 1		14 Apr 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-005F1AE2		CARRY OUT 6 MTHLY L2 TASKS IAW AESP2320-D-122-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 2		14 Apr 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-00613A76		RENEW BRAKE FLUID IAW AESP-2320-D-128-601 TABLE 5	Closed	Non-Taskworthy	No	Level 2		15 Jun 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-00613A60		RENEW ALL 4 STUB AXLES & WHEEL BRGS	Closed	Non-Taskworthy	No	Level 2		15 Jun 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-00613A5A		RENEW ALL 4 BRAKE DISCS & PADS & NEW REAR CALIPERS	Closed	Non-Taskworthy	No	Level 2		15 Jun 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-00613A4D		CARRY OUT 6 MTHLY L1 (REPEAT) TASKS IAW AESP2320-D-122-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 1		15 Jun 2011	N/A	Servicing	TUL HS GS SOFT TOP			
000000-006141B8		INSPECTION OF STEERING DROP ARM IAW AESP2320-D-128-522 CH 7 PG 23 SER 35 & AESP 2320-D-122-522 CH 7-1 PG 17 SER 22 LETTER DTD 10/06/11	Closed	Non-Taskworthy	No	Level 2		15 Jun 2011	N/A	Inspection	TUL HS GS SOFT TOP			
000000-005D0C3B9		HEAD LIGHT IN-OP (ELECTRICAL PROBLEM) DVR'S SIDE	Closed	Non-Taskworthy	No	Level 1		11 Feb 2011	N/A	Failure	TUL HS GS SOFT TOP			
000000-005883DA	000000-002CF9B	CARRY OUT YRLY L1 (REPEAT) TASKS IAW AESP-2320-D-128-601 TABLE 7 COL B	Closed	Non-Taskworthy	No	Level 1		12 Nov 2010			TUL HS GS SOFT TOP			
000000-0059573F	000000-002CC69F	CARRY OUT YRLY L2 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL B	Closed	Non-Taskworthy	No	Level 2		28 Sep 2010			TUL HS GS SOFT TOP			
000000-005957BA	000000-002C74A8	CARRY OUT OOP L1 TASKS RENEW GEAR BOX OIL IAW AESP-2320-D-128-601 TABLE 5	Closed	Non-Taskworthy	No	Level 1		28 Sep 2010			TUL HS GS SOFT TOP			
000000-0059573C	000000-002C74A8	CARRY OUT YRLY L1 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL B	Closed	Non-Taskworthy	No	Level 1		28 Sep 2010			TUL HS GS SOFT TOP			
000000-005A5244	000000-002D03C3	RENEW SPARE WHEEL LIFTING HARNESS (WEBBING CUT)	Closed	Fully Fit	No	Level 2		18 Oct 2010			TUL HS GS SOFT TOP			
000000-005A523D	000000-002D03C3	SECURE RH DOOR INNER TRIM	Closed	Fully Fit	No	Level 2		18 Oct 2010			TUL HS GS SOFT TOP			
000000-005A5238	000000-002D03C3	MAP LIGHT INOP	Closed	Fully Fit	No	Level 2		18 Oct 2010			TUL HS GS SOFT TOP			
000000-00595789	000000-002C7EF8	CARRY OUT AFG 932B MEI DUE 09 NOV 10	Closed	Non-Taskworthy	No	Level 2		28 Sep 2010			TUL HS GS SOFT TOP			
000000-0057A768	000000-002C550A	R/H/R SEAT BRACKET REQUIRES SECURING	Closed	Non-Taskworthy	No	Level 1		16 Sep 2010			TUL HS GS SOFT TOP			
000000-0057A74D	000000-002C5502	HANDBRAKE REQUIRES ADJUSTING	Closed	Non-Taskworthy	No	Level 2		16 Sep 2010			TUL HS GS SOFT TOP			
000000-004EF8BF	000000-002AE7FD	LEAK LHS REAR ROCKER COVER	Closed	Fully Fit	No	Level 2		01 Apr 2010			TUL HS GS SOFT TOP			
000000-004ECD3C	000000-002ADD04	CARRY OUT AFB 6534 INSP	Closed	Non-Taskworthy	No	Level 1		29 Mar 2010			TUL HS GS SOFT TOP			
000000-004ECCBD	000000-002AE7FC	CARRY OUT 6 MTHLY L2 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 2		29 Mar 2010			TUL HS GS SOFT TOP			
000000-004ECCB8	000000-002ADD00	CARRY OUT 6 MTHLY L1 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 1		29 Mar 2010			TUL HS GS SOFT TOP			
000000-004EF8D8	000000-002AE7FA	RENEW REAR REVERSE LIGHT LENS	Closed	Fully Fit	No	Level 1		01 Apr 2010			TUL HS GS SOFT TOP			
000000-004ECD3F	000000-002ADD07	CARRY OUT WEEKLY INSPECTION	Closed	Non-Taskworthy	No	Level 1		29 Mar 2010			TUL HS GS SOFT TOP			
000000-004DEC61	000000-002AB0D9	RENEW FRONT PASSENGER MUD FLAP	Closed	Fully Fit	No	Level 2		09 Mar 2010			TUL HS GS SOFT TOP			
000000-004DED78	000000-002AB121	MAP LIGHT U/S	Closed	Fully Fit	No	Level 2		09 Mar 2010			TUL HS GS SOFT TOP			
000000-004DF8C5	000000-002AB348	L/H/F BRAKE DISC SHIELD BRACKET U/S	Closed	Non-Taskworthy	No	Level 2		10 Mar 2010			TUL HS GS SOFT TOP			
000000-004DF8BF	000000-002AB348	NO REVERSE TRAVEL ON HANDBRAKE	Closed	Non-Taskworthy	No	Level 2		10 Mar 2010			TUL HS GS SOFT TOP			
000000-004DFC88		FIRST PARADE	Closed	Non-Taskworthy	No	Level 2		10 Mar 2010			TUL HS GS SOFT TOP			
000000-004DEC0E	000000-002AB0D0	RENEW BROKEN FRONT PASSENGER SIDE MUD FLAP	Closed	Fully Fit	No	Level 2		09 Mar 2010			TUL HS GS SOFT TOP			
000000-00489FC6	000000-002A3D62	WINDSCREEN WIPER INOP	Closed	Non-Taskworthy	No	Level 2		15 Jan 2010			TUL HS GS SOFT TOP			
000000-00497108	000000-0029D89E	RENEW DIFFY RH/F HEADLIGHT GUARD FASTENER	Closed	Fully Fit	No	Level 2		09 Nov 2009			TUL HS GS SOFT TOP			
000000-004852D1	000000-0029A368	REMOVE SHEARED TRANSFER DRAIN PLUG, DRAIN AND REFILL OIL	Closed	Non-Taskworthy	No	Level 3		08 Oct 2009			TUL HS GS SOFT TOP			
000000-004863F3	000000-0029D683	CARRY OUT RECEIPT INSPECTION/MEI AF G932B OVERDUE AS @ 09/10/09	Closed	Non-Taskworthy	No	Level 2		06 Nov 2009			TUL HS GS SOFT TOP			
000000-0047CFB8	000000-002988A7	RENEW BROKEN CONVOY LIGHT ASSY	Closed	Limited Role	No	Level 2		23 Sep 2009			TUL HS GS SOFT TOP			
000000-0047D264	000000-002988A3	RENEW BRAKE FLUID IAW AESP-2320-D-128-601 TABLE 5	Closed	Non-Taskworthy	No	Level 2		23 Sep 2009			TUL HS GS SOFT TOP			
000000-0047D263	000000-002988A3	CARRY OUT 2 YRLY L2 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL C	Closed	Non-Taskworthy	No	Level 2		23 Sep 2009			TUL HS GS SOFT TOP			
000000-0047CF9F	000000-002988A3	REMOVE SHEARED TRANSFER DRAIN PLUG, DRAIN AND REFILL OIL	Closed	Non-Taskworthy	No	Level 2		23 Sep 2009			TUL HS GS SOFT TOP			
000000-0047C578	000000-002985CC	CARRY OUT 2 YRLY L1 TASKS IAW AESP-2320-D-128-601 TABLE 7 COL C	Closed	Non-Taskworthy	No	Level 1		22 Sep 2009			TUL HS GS SOFT TOP			
000000-0040EE20	000000-0028AD4D	REPLACE RHR TYRE (ON DEMAND)	Closed	Non-Taskworthy	No	Level 1		01 Apr 2009			TUL HS GS SOFT TOP			
000000-0040DAEE	000000-0028AA8B	CARRY OUT AF B 6534 DUE 9 APR 09	Closed	Non-Taskworthy	No	Level 1		31 Mar 2009			TUL HS GS SOFT TOP			
000000-0040A68F	000000-0028A92B	CARRY OUT L1 TIS 6 MTHLY IAW AESP-2320-D-128-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 1		30 Mar 2009			TUL HS GS SOFT TOP			
000000-0040EDA8	000000-0028AD39	CHIP IN WINDSCREEN BELOW DRV WIPER BLADE	Closed	Non-Taskworthy	No	Level 2		01 Apr 2009			TUL HS GS SOFT TOP			
000000-0040EDA6	000000-0028AD39	WRONG SEATBELT STALK FITTED PASS SIDE	Closed	Non-Taskworthy	No	Level 2		01 Apr 2009			TUL HS GS SOFT TOP			
000000-0040EDA2	000000-0028AD39	RENEW PASSENGER DOOR CHECK BLOCK	Closed	Non-Taskworthy	No	Level 2		01 Apr 2009			TUL HS GS SOFT TOP			
000000-0040ED98	000000-0028AD39	RENEW FRONT NUMBER PLATE	Closed	Non-Taskworthy	No	Level 2		01 Apr 2009			TUL HS GS SOFT TOP			
000000-0040ED98	000000-0028AD39	RHR (NEW) SHOCK LEAKING	Closed	Non-Taskworthy	No	Level 2		01 Apr 2009			TUL HS GS SOFT TOP			
000000-0040ED94	000000-0028AD39	RESET ACCEL PEDAL STOP	Closed	Non-Taskworthy	No	Level 2		01 Apr 2009			TUL HS GS SOFT TOP			
000000-0040ED92	000000-0028AD39	CARRY OUT 6 MTHLY L2 TASKS IAW AESP-2320D-128-601 TABLE 7 COL A	Closed	Non-Taskworthy	No	Level 2		01 Apr 2009			TUL HS GS SOFT TOP			
000000-003D9944	000000-002886C8	REAR PASSENGER SHOCK ABSORBER BUSH WORN CAUSING RATTLING NOISE WHILST DRIVING	Closed	Non-Taskworthy	No	Level 2		28 Feb 2009			TUL HS GS SOFT TOP			
000000-003ED3DE	000000-00289659	CARRY OUT L1 OOP TASK. RENEW AIR CLEANER IAW AESP -2320-D-128-601 TABLE 5	Closed	Non-Taskworthy	No	Level 1		12 Mar 2009			TUL HS GS SOFT TOP			
000000-002FBFBC		Initial Usage	Closed	Fully Fit	No	Level 1		07 Nov 2008			TUL HS GS SOFT TOP			
000000-002FC1A6		Initial Maintenance	Closed	Fully Fit	No	Level 1		07 Nov 2008			TUL HS GS SOFT TOP			