

Product Recall

Salety & Standards Product Recall	
MAHABUB MP-0758 Silver Incense Burner	
Aspect	Details
Images	Incense Burner Incense Burner
Alert Number	2212-0147
Product Type	Electrical Appliances and Equipment – Incense Burner
Product Identifiers	Brand: MAHABUB Model Number: MP-0758
Product Description	Metal ornate incense burner with red power switch, black power supply cord and clover leaf plug, supplied in a white and green cardboard box with an image of the product on the face.
Country of Origin	China
Counterfeit	No
Risk Type	Electric Shock
Risk Level	Serious
Risk Description	The product presents a serious risk of electric shock as it is supplied with a clover leaf plug. Clover leaf plugs do not meet the requirements of the relevant standard BS 1363 as they are not fused, and the edge of the plug face is too small a distance from the pins. Users can access live parts when they are unplugging, or plugging in, the product. The earth pin was also sleeved, meaning the product is not fully earthed when in use. The plug pins also possessed noncompliant dimensions, which could cause damage to the plug socket. Accessible conductive parts were separated from live parts only by basic insulation, meaning the product could become live under fault conditions. The product was also missing required labelling, markings and documentation. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.
Corrective Measures	The product has been recalled from end users and withdrawn from the market by the distributor Master News (AG Food and Wine Limited).
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts