

4<sup>th</sup> Floor, Cannon House 18 The Priory Queensway Birmingham B4 6BS +44 (0) 121 345 1201

## **Enforcement Undertaking Summary**

## Electric Vehicles (Smart Charge Points) Regulations 2021

An Enforcement Undertaking is a commitment by a business to undertake specific actions within a specified timeframe.

The Office for Product Safety and Standards ('OPSS') has accepted an Enforcement Undertaking under paragraph 20, Schedule 2 to the Electric Vehicles (Smart Charge Points) Regulations 2021 ('the Regulations') as summarised below:

Date Enforcement Undertaking starts	30 December 2022
Date by which all actions specified in the Enforcement Undertaking must be completed	01 July 2023

Name of business:	Schneider Electric (UK) Limited
<b>Company registration number:</b> (if applicable)	02886434
Address: (including postcode)	Stafford Park 5 Telford Shropshire TF3 3BL

Model(s) or type(s) of charge point covered by the Enforcement Undertaking

1. EVlink Pro AC

2. EVlink Pro AC Metal

## Technical requirement(s) addressed in the Enforcement Undertaking

1. Regulation 12 - Security

## **Enforcement Undertaking**

Model or Type of charge point	Breach(es)	Action(s)	Completion Date	
Action(s) to secure that the breach(es) do not continue or recur.				
Evlink Pro AC and EVlink Pro AC Metal	Regulation 12	Software update to be issued to address areas of non-compliance.	01 July 2023	
Action(s) to secure the restoration of the position, in so far as possible, to what it would have been if the breach(es) had not been committed.				
Evlink Pro AC and EVlink Pro AC Metal	Regulation 12	Software update to be issued to address areas of non-compliance.	01 July 2023	
Action(s) (including the payment of any sums of money) to benefit any third parties affected by the breach(es).				
How the statement of compliance will reflect the areas of compliance with the Regulations, and any areas of non-compliance, for the respective charge point:				
Statement of Compliance will show adherence to regulations and outline the areas not compliant and that a firmware update will be method of gaining full compliance.				