



<b>VEVOR Sealing Machine</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2203-0285
<b>Product Type</b>	Machinery – Sealing Machine
<b>Product Identifiers</b>	Brand: Vevor Model: FR-900 Other Product Identifiers: RVG3355-210913-0005-186, GBLFD-GC0030, G3355-FR900BMFKJ000001V2
<b>Product Description</b>	Grey and blue machine with black power supply cord and plug, supplied in brown cardboard packaging.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	Unknown – plug and fuse are counterfeit
<b>Risk Level</b>	Serious
<b>Risk Type</b>	Electric Shock
<b>Risk Description</b>	<p>The product presents a serious risk of electric shock as the earthing arrangements are insufficient. There is inadequate earth bonding, meaning accessible metal parts can become live under fault conditions. If a user were to touch accessible metal parts, they would receive an electric shock. The product's plug also did not meet the dimensional requirements of the relevant standard, BS 1363, because the live and neutral pins are too close to the edge of the plug face, making them accessible when the plug is being inserted to, or removed from, the socket.</p> <p>The product does not meet the requirements of the Supply of Machinery (Safety) Regulations 2008 or the Plugs &amp; Sockets (Safety) Regulations 1994.</p>
<b>Corrective Measures</b>	<p>The product has been recalled from end users. For further information, access the Vevor recall webpage at: <a href="https://uk.vevor.com/pages/Product-Recall-Statement">https://uk.vevor.com/pages/Product-Recall-Statement</a></p> <p>The import has been rejected at the border and destroyed.</p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards