




Raymarine ACU-150 / ACU-400 Autopilot System	
Aspect	Details
Images	
Alert Number	2307-0191
Product Type	Recreational crafts - Autopilot System
Product Identifiers	This recall affects the following ACU-150 and ACU-400 serial number ranges only: ACU-150 (E70430) serial numbers 0720203, 0620001 - 0720131 and ACU-400 (E70100) serial numbers 0420339, 0920329 and 0620001 - 0720151
Product Description	Black actuator control unit with brand "Raymarine" printed on
Country of Origin	Unknown
Counterfeit	No
Risk Type	Injuries
Risk Description	Raymarine has identified that certain ACUs manufactured between June and July 2022 were fitted with a drive component of incorrect specification. Whilst the ACUs may function correctly, there is a risk that the affected component could fail prematurely. This could prevent the ACU from driving in one or both directions or cause it to turn the tiller / wheel fully in one direction, potentially giving rise to a loss of directional control unless or until the system is disconnected.
Corrective Measures	Recall of the product from end users. For more information, please see: https://www.raymarine.com/en-gb/support/acu-150-acu-400-product-recall
Online Marketplace	N/A
Notifier	Local Authority Trading Standards