

**NOTICE OF AUTHORIZED AMENDMENT: MAA/NAA/24/53** 

RA(s) or Manual Chapter(s):			RA 2135 - Aircrew and Supernumerary Crew Medical Requirements				
RFC Reference(s):			MAA/RFC/2023/134, 2024/081				
NPA Reference(s):			NPA 24/43				
MAA Author	Post	MAA-Reg-Fly1					
	Name	Redacted					
	Rank	Redacted			Redact	ed - Original Signed	
MAA Supervisor	Post	MAA-Reg-Fly					
	Name	Redacted					
	Rank	Redacted			Redacted - Original Signed		
MAA Independent	Post	MAA-Reg-ATM2					
	Name	Redacted					
	Rank	Redacted			Redact	ed - Original Signed	
	Post	N/A					
MAA LegAd (if required)	Name	N/A					
	Rank	N/A			N/A		
Amendment Classification Minor Ch		nange		Publish	ning ements:	Next regular release	

Ref No: MAA/NAA/24/53

Cross-references to Other Documents or Relevant Sources				
Other MRP Amendments	Nil			
Service Inquiry Recommendations	Nil			
AAIB Recommendations	NII			
Other Investigation Recommendations	Nil			
Any Other Document	Nil			

Version 7 Page 1 of 2



Ref No: MAA/NAA/24/53

## **Authorized Amendment**

Summary / Overview of the amendment to explain/ensure that the reader understands: the rationale for the amendment; the major changes; and, importantly, the full context (including desired outcome) of the amendment.

The Regulated Community is reminded to check this amendment against any applicable AAMC, Waivers or Exemptions to ensure their ongoing validity.

RA 2135(1) is amended to reflect that the DH does not set a MES for Aircrew. The standards are set by med policy through AP1269A via the role JPAN. This RA's intent is that the DH should ensure that crew's MES and fitness to fly are managed iaw AP1269A and medical advice.

ISSUE STATE CHANGES (if more lines required, contact the MRP Team)				
Document Title	Previous Issue	New Issue		
RA 2135 - Aircrew and Supernumerary Crew Medical Requirements	Issue 12 To	Issue 13		

	Post	OpAssure-Op-DepHd	
Approval	Name	Redacted	
	Rank	Redacted	Redacted - Original Signed

Version 7 Page 2 of 2