




<b>SPRiNTUS BoostiX iGo and BoostiX 36V Vacuum Cleaners</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>PSD Number</b>	2407-0098
<b>Product Type</b>	Electrical appliances and equipment – Vacuum Cleaner
<b>Product Identifiers</b>	Brand: SPRiNTUS Products: BoostiX iGo and BoostiX 36V Model/type: 119002
<b>Product Description</b>	Vacuum cleaner designed to be used/worn as a backpack.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	No
<b>Risk Level</b>	Low
<b>Risk Type</b>	Fire
<b>Risk Description</b>	<p>The product presents a risk of fire and explosion.</p> <p>If there is a current peak, such as a shortcut on the Printed Circuit Board (PCB) of the motor, the Battery Management System may get overloaded and become damaged.</p> <p>The product does not meet the requirements of the General Product Safety Regulations 2005.</p>
<b>Corrective Measures</b>	<p>The manufacturer has initiated a modification programme to upgrade affected products with an additional fuse.</p> <p>End users will be contacted directly by distributors to provide instructions on upgrading their machine.</p> <p>Additional information can be requested from the manufacturer via the following email address: <a href="mailto:boostix@sprintus.eu">boostix@sprintus.eu</a>.</p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Office for Product Safety and Standards